



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

DATE: 27/06/2022

### Survey details

|                     |                            |
|---------------------|----------------------------|
| Date of loss        | 21/6/2022                  |
| Date of appointment | 22/6/2022                  |
| Date of survey      | 23/6/2022                  |
| Location of survey  | ASSURE AUTO ASSIST PTE LTD |

### Vehicle Details:

|                      |                                    |
|----------------------|------------------------------------|
| Claim Type:          | THIRD PARTY                        |
| Vehicle number       | SKZ2172G                           |
| Make and Model       | MERCEDES BENZ E250 SEDAN EDITION E |
| Date of registration | 14/1/2016                          |
| Excess               |                                    |
| Market Value         | \$111,000.00                       |
| Parf Rebate          | \$63,234.00                        |
| Nett Loss            | \$47,766.00                        |

### Repair details

|                  |  |
|------------------|--|
| Initial Estimate |  |
|------------------|--|

### Proposed/Revised repair cost:

|                          |              |
|--------------------------|--------------|
| Parts                    |              |
| "Check items (Estimated) |              |
| Labour                   |              |
| Total                    |              |
| Lump Sum (Estimated)     |              |
|                          |              |
| Number of days of repair | 4 days (est) |

### **Remarks:**

The estimated repair cost of the damaged vehicle is in the region of \$3,000.00-\$4,000.00