



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22005957/Ucy3e2	
			Date: 15/09/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJC 4417X	Veh. Inspected	XE 6683D
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2202160/RUC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	22/06/2022
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ ECONIC 2630L	c.c	7698
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	W1T9560332V266544	Colour	SILVER
	Odometer	62678 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	315/80 R22.5	BRIDGESTONE	6 mm
	L/H Front Tyre	315/80 R22.5	BRIDGESTONE	6 mm
	R/H Rear Tyre	315/80 R22.5 (D/D)	BRIDGESTONE	6/6/6/6 mm
	L/H Rear Tyre	315/80 R22.5 (D/D)	BRIDGESTONE	6/6/6/6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	25/04/2022	Inspection Date	24/06/2022
	Survey held at	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339		
5a. Remarks				
	A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS.. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	