

**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) )

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	280G
<b>Vehicle Details</b>	
Vehicle No.:	XE6683D
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Jun 2022
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	ECONIC 2630L ENA 6X2/4 3900 (AUTO,ABS)
Primary Colour:	White
Manufacturing Year:	2021
Engine No.:	936973C0232807
Chassis No.:	W1T9560332V266544
Maximum Power Output:	-
Open Market Value:	\$166,362.00
Original Registration Date:	19 Aug 2021
First Registration Date:	19 Aug 2021
Transfer Count:	0
Actual ARF Paid:	\$8,319.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	18 Aug 2031
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$39,523.00
COE Rebate Amount:	\$36,165.00
Total Rebate Amount:	\$36,165.00

The information contained herein is correct as at 24 Jun 2022

OK





Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR XE6683D

SembWaste Pte Ltd

30 Hill Street  
#05-04  
Singapore 179360  
  
67233200A/C

## Vehicle &amp; Document Information

WIP No 55670  
Reg No/Reg Date XE6683D / 19/08/2021  
Date In/Mileage XE6683D  
Chassis No W1T9560332V2665444  
Engine No 936973C0232807  
Make/Model MBCV/Econic New 2630L ENA 6X2/  
Colour/Trim 914 Arctic White / NA NOT APPLICABLE

Account No	Terms	Date/Time Printed	CSE	Operator
WS000458	Credit	28/04/2022/ 10:01	Gea	610 / Philip Cheong

Description of Goods / Services

Qty	Unit Price	Disc%	Amount
		35.00	624.00

A 00940101

FRONT LEFT PAINTING

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

not Authorized  
for merous  
work photo After repair  
tel: 62563561  
MP 90096608  
02 days

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirmed &amp; accepted by

Nett	624.00
7% GST on	43.68

Total Payable 667.68

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Gardens MBCV Customer Service Center  
209 Pandan Gardens  
Singapore 609339  
Tel: (65) 67714389  
Fax: (65) 67756310  
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG