

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 29 June 2022 11:03 AM
To: Grace Tan
Cc: SUR
Subject: RE: ECICS-OD SLR 3717J DOA: 17/06/2022

Dear Grace,

Please proceed to repair the insured vehicle SLR 3717J at repair cost on part by part basis.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Grace Tan <Grace@Ricardo.com.sg>
Sent: Wednesday, 29 June 2022 10:40 AM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: RE: ECICS-OD SLR 3717J DOA: 17/06/2022

Hi Shiau Chan,

Any update?

Kind Regards,

Grace Tan
Ricardo Auto Centre Pte Ltd

160 Sin Ming Drive #02-02/03
Sin Ming AutoCity
Singapore 575722

T: 6475 2112 (Main)
6460 9542 (DID)
F: 6475 4666
W: www.ricardo.com.sg

Save Paper. Save the Earth. Think twice before you print.

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Monday, 27 June 2022 4:46 pm
To: Grace Tan <Grace@Ricardo.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: ECICS-OD SLR 3717J DOA: 17/06/2022

Dear Sir/Madam,

As instructed by our client, please proceed to repair the insured vehicle **SLR 3717J at repair cost not more than \$2,500.00 on Lump Sum basis or whichever lower (Excess \$0/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)