



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

26/8/2022

Survey Details:

Date of loss	20-Jun-22
Date of appointment	23-Jun-22
Date of survey	23-Jun-22
Location of survey	HUP LEY HUAT MOTOR SPRAY PAINTING SVS

Vehicle Details:

Claim Type:	Third Party Claim
Vehicle number	SFZ 536M
Make and Model	HONDA CRV 2.0L AT
Date of registration	1/12/2009
Excess	-
Market Value	\$ 17,000.00
Parf Rebate	\$ 8,934.00
Nett Loss	\$ 8,066.00

Repair details:

Initial Estimate	\$ -
------------------	------

Proposed/Revised repair cost:

Parts	
Check items (estimate)	
Labour	
Total	\$ -
Lump Sum(if applicable)	

Number of days for repair	<u>7</u>
----------------------------------	----------



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

The estimate repair cost of the damaged vehicle is in the region of \$7,000.00 - \$8,000.00.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$	no. of days
Loss of rental	\$	no. of days
Loss of income	\$	no. of days
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	