

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/CT/2205979/4643

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

T 7138
Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2071300

29/6/22 P/P & 2123.90 informed shug, (Red 651/-, 23%)

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐

: Preli. Report

☒

: Final Report

Days Of Repair:

3

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

TP

Lump Sum / (B.): (\$ 2,123.90)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle


Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	713D
Vehicle Details	
Vehicle No.:	FBR3062H
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Jun 2022
Vehicle Make:	YAMAHA
Vehicle Model:	T150
Primary Colour:	Yellow
Manufacturing Year:	2020
Engine No.:	G3P3E0001349
Chassis No.:	MH3UG131000001316
Maximum Power Output:	-
Open Market Value:	\$2,068.00
Original Registration Date:	02 Apr 2020
First Registration Date:	02 Apr 2020
Transfer Count:	1
Actual ARF Paid:	\$311.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	01 Apr 2030
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$4,310.00
COE Rebate Amount:	\$3,350.00
Total Rebate Amount:	\$3,350.00

The information contained herein is correct as at 23 Jun 2022

OK

Posted on : 06/05/2022

★ Direct Seller

[Details >](#)**Yamaha T135 Spark**

Reg Date : 21/12/2011

Capacity : 135cc

Vehicle Type : Cubs

Mileage : 65111km

SGD \$6000

Posted on : 05/05/2022

★ Direct Seller

[Details >](#)**Yamaha Sniper 150**

Reg Date : 03/02/2020

Capacity : 150cc

Vehicle Type : Cubs

Mileage : 21000km

SGD \$12000

Posted on : 28/04/2022

★ Direct Seller


[Details >](#)[first](#) [previous](#) [1](#) [2](#) [last](#)**Bike Gadgets**

- Number Plates for Sale
- Installment Calculator
- Instant Insurance Quote

COE Results

Rd 2, 22 Jun 2022
COE Bidding of Motorcycles

CAT D
\$10302



Reg Date : 07/07/2014

Capacity : 125cc

Vehicle Type : Cubs

Mileage : 73000km

SGD \$4500

Posted on : 29/05/2022

★ Direct Seller

[Details >](#)

Honda Wave 125

Reg Date : 11/12/2009

Capacity : 125cc

Vehicle Type : Cubs

Mileage : -

SGD \$8000

Posted on : 28/05/2022

★ Direct Seller

[Details >](#)

Yamaha Aerox 155

Reg Date : 21/06/2021

Capacity : 155cc


Vehicle Type : Cubs

Mileage : 13370km

SGD \$13000

Posted on : 27/05/2022

★ Direct Seller

[Details >](#)

Yamaha T135 Spark

Reg Date : 13/03/2009

Capacity : 135cc

Vehicle Type : Cubs

Mileage : 62000km

SGD \$3000

Posted on : 27/05/2022

★ Direct Seller

[Details >](#)

CASH SALES / WORK ORDER

SWIFT MOTORBIKES & SCOOTERS RECOVERY

Co. Reg No. : 53354658C

NO. 04906

Date: 200622

宝号

Messrs: (GSH)

车号

Vehicle No: FBL7036

由

From: Bunggo/On

备注

Remarks: 90904035 HF

车型

Model No: Burgman / Y15Z

到


To: 738

Cash \$: 90/-

注意: 本公司对所拖之车辆, 在进行中如有任何损失或破坏, 一概由车主自行负责。
NOTE: Vehicle is transported at owner's risk. The company accepts no responsibility for damages or other misdeemeanour to your vehicle whilst being transported.

Received by

Issued By



張 噴 漆 TEO SPRAY PAINTING

(INCORPORATED IN THE REPUBLIC OF SINGAPORE)
Reg. Address: BLOCK 6, DEFU LANE 10, DEFU INDUSTRIAL PARK C, #01-558
SINGAPORE 539187 TEL: 6283 5474 (2 LINES) FAX: 6287 2012
REG. NO. 275084 / 00X

China Taiping Insurance (S,pore) Pte Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909
Tel: 6389 6111
Fax:6222 1033

2/1/23 2123.90

Not Authorized
Lunoray

23/06/22

90096608

Dear Sir/Madam

22.06.2022


RE: THIRD PARTY CLAIMS FOR FBR3062H AGAINST YOUR
INSURED SJW4568M , ACCIDENT ON 17.06.2022 AT
PAN ISLAND EXPRESSWAY

4/53
3 days.
who/ble the rep
2/1/23

PG 1

DESCRIPTION	AMOUNT
1 FRONT FORK <i>but / 1/2</i>	\$ 350.00 <i>2/1</i>
2 UNDERBRACKET <i>but</i>	\$ 280.00 <i>2/1</i>
3 STEERING CONE <i>net</i>	\$ 95.00 <i>2/1</i>
4 FRONT FENDER <i>one</i>	\$ 38.00 <i>✓</i>
5 FRONT DISC <i>11</i>	\$ 95.00 <i>X</i>
6 FRONT RIM <i>R</i>	\$ 280.00 <i>X</i>
7 HORN COVER <i>cut</i>	\$ 48.00 <i>✓</i>
8 LAMP BLACK COVER <i>Re</i>	\$ 45.00 <i>✓</i>
9 HANDLE BAR <i>sk</i>	\$ 65.00 <i>X</i>
10 BALANCER RH <i>ms</i>	\$ 48.00 <i>✓</i>
11 FRONT PILOT LIGHT <i>11</i>	\$ 250.00 <i>X</i>
12 FRONT SIDE COVER RH <i>em</i>	\$ 48.00 <i>✓</i>
13 FRONT SIGNAL LH <i>scat</i>	\$ 48.00 <i>✓</i>
14 FRONT FOOTREST <i>HH RH 320</i>	\$ 35.00 <i>✓</i>
15 REAR BRAKE PANEL <i>but</i>	\$ 45.00 <i>✓</i>
16 FOOTREST BRACKET <i>but</i>	\$ 45.00 <i>✓</i>
17 TAIL COVER LH <i>one</i>	\$ 50.00 <i>✓</i>
18 TAIL COVER RH <i>one</i>	\$ 50.00 <i>✓</i>
19 PILLION BAR <i>cut</i>	\$ 120.00 <i>✓</i>
20 EXHAUST PROTECTOR <i>cut</i>	\$ 45.00 <i>✓</i>
21 EXHAUST COVER <i>cut</i>	\$ 45.00 <i>✓</i>
22 REAR SIGANL LH <i>320</i>	\$ 40.00 <i>✓</i>
	\$ 2,165.00
Less 10%	\$ 216.50
Sub Total	\$ 1,948.50

1475



張 噴 漆 TEO SPRAY PAINTING

(INCORPORATED IN THE REPUBLIC OF SINGAPORE)

Reg. Address: BLOCK 6, DEFU LANE 10, DEFU INDUSTRIAL PARK C, #01-558
SINGAPORE 539187 TEL: 6283 5474 (2 LINES) FAX: 6287 2012
REG. NO. 275084 / 00X

PG 2

Nett Item			
1 TOP BOX	cup	\$ 250.00	✓
2 BOX RACK	24	\$ 150.00	✓
3 TRANSPORT		\$ 60.00	✓
4 LABOUR CHARGES		\$ 280.00	250
Sub Total		\$ 740.00	
Total		\$ 2,688.50	2774.90

THANKS
TSP

P-1571
10%
1413.90
710
2123.90


LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



張 噴 漆
TEO SPRAY PAINTING

(INCORPORATED IN THE REPUBLIC OF SINGAPORE)

Reg. Address: BLOCK 6, DEFU LANE 10, DEFU INDUSTRIAL PARK C, #01-558

SINGAPORE 539187 TEL: 6283 5474 (2 LINES) FAX: 6287 2012

REG. NO. 275084 / 00X

China Taiping Insurance (S,pore) Pte Ltd.

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

Tel: 6389 6111

Fax:6222 1033

Dear Sir/Madam

28.06.2022

RE: THIRD PARTY CLAIMS FOR FBR3062H AGAINST YOUR
INSURED SJW4568M , ACCIDENT ON 17.06.2022 AT
PAN ISLAND EXPRESSWAY

<u>Supplementary</u>	Amount
1 LOWER BLACK COVER LH Cu7	\$ 48.00 ✓
2 LOWER BLACK COVER RH Cu7	\$ 48.00 ✓
SUB TOTAL	\$ 96.00
LESS 10%	\$ 9.60
	<u>\$ 86.40</u>

Thank you.

Teo spray

Shuqi