

ASS. REC. BY:

REF: III / CS/III22005988/Kqy3

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Cheng Hoe

of _____ 313K

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$89k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 1.B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: PC 9605M Yr Regn: 03, 21

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A)

Make: Toy Hiace c.c. 2982

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 27980 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTSFT 22 P 30 00 40327

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: 195R 15X8

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 8 mm R/Bal. 8 mm

L/Bal. 8 mm L/Bal. 8 mm

D.O.A. 17/6/22 D.O.I. 23/6/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

- 23/06/22 @ 5.41pm revert to III via Merimen.
- 27/06/22 @ 11.13am Gabriel Wee informed C/A via Merimen.
- 27/06/22 @ 11.44am Informed wksp C/A & ex: \$2000 by email.


Date/Time, File Pass to? : Prell. Report
 : Final Report

Days Of Repair: _____
Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Survey Fee:	
Transportation:	
S - R.S. \$	
Fixturs	
Others	
TOTAL	

Report Format : _____
Lump Sum / I.B.I: (\$)



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761
Tel : 67556142 Fax : 67557719
Email: chmotor@singnet.com.sg

INSURER: **India International Insurance Pte Ltd (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/INDIA
Policy No:	D22MFL0001917	Date of Loss:	17/06/2022
Vehicle Reg. No.:	PC9606M	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	COMFORTDELGRO MEDCARE PTE LTD		
Driver:	CHNG KAH HOE		

Make/Model:	TOYOTA HIACE, 3.0 D HIGH ROOF COMMUTER TURBO (A)	Vehicle Reg. Date:	26/03/2021
Vehicle Colour:	WHITE	Chassis No:	JTFST22P300040327
Engine No:	1KDB069053		
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	0

*Not with white
Painting B & pain
Ex TBA
6 days*

Remarks: VEHICLE CURRENTLY LYING AT YISHUN WORKSHOP.

Present Location: CHENG HOE MOTOR PTE LTD (YISHUN)

COST OF CLAIMS	Amount
Parts	1,518.00
Miscellaneous Items	106.00
Labour	1,780.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	3,404.00
+ GST 7.00% (\$)	238.28
Nett Amount (\$)	3,642.28

This claim is handled by: SHARON CHIONG BENG CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

PC9606M
OD/India

Reference

Part Source: (Last Synchronised: 23 Jun 2022)
Parts: N/A TOYOTA HIACE 3.0 D HIGH ROOF COMMUTER TURBO (A) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Cheng Hoe Motor Pte Ltd/PC9606M/23/06/2022 13:10
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC REAR BUMPER	0.00	0.00	R ₁ *155.00 F ✓
2	1		*6 PCS REAR BUMPER CLIPS @2/PC	0.00	0.00	N ₁ *12.00 F ✓
3	1		*1 PC TAILGATE	0.00	0.00	R ₁ *850.00 F ✓
4	1		*1 PC TAILGATE LOGO	0.00	0.00	N ₁ *38.00 F ✓
5	1		*1 PC TAILGATE INNER LOCK	0.00	0.00	R ₁ *125.00 F ✓
6	1		*1 PC TAILGATE STICKER (HIACE)	0.00	0.00	N ₁ *30.00 F ✓
7	1		*1 PC REAR PANEL OUTER	0.00	0.00	R ₁ *170.00 F ✓
						F=Franchise part.
Sub Total (\$\$)						1,380.00
+ Margin on L,N Items 10.00% (\$\$)						138.00
Total Parts (\$\$)						1,518.00

Cheng Hoe Motor Pte Ltd/PC9606M/23/06/2022 13:10. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	1 PC HANDICAPPED STICKER	N ₁ 30.00 ✓
2	1	1 PC REAR WINDSCREEN GLASS GUM	N ₁ 40.00 ✓
3	1	1 PC STICKER - 60KM/H	N ₁ 10.00 ✓
4	1	1 PC STICKER - ME 106	N ₁ 15.00 ✓
5	1	OD/TP Case (Insurer)	N ₁ 11.00 ✓
		1 set reverse sensor #280/4d ?	
Sub Total (\$\$)			106.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	REMOVE & REFIX REAR WINDSCREEN GLASS		✓
2	REMOVE & REFIX REAR BUMPER ASSY, TAILGATE, REAR WIPER ASSY, LOCK ASSY, TO CUT, WELD & RENEW REAR PANEL OUTER AND REALIGN THE SAME	New	100.00
		New	850.00
3	PUTTY & RESPRAY ON REAR END PANEL, REAR BUMPER, TAILGATE		
4	REMOVE & REFIX REVERSE CAMERA, CCTV RECORDER, REVERSE SENSOR AND RESET SYSTEM	New	860.00
		New	80.00
⑤ Advertisement - \$250 ? (Included)			
Gross Labour Cost (\$\$)			1,780.00

Cheng Hoe Motor Pte Ltd/PC9606M/23/06/2022 13:10. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATE

LRK Auto Consultants hereby notify the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 313K

Vehicle Details

Vehicle No.: PC9606M
Vehicle to be Exported: Yes
Intended Deregistration Date: 22 Jun 2022
Vehicle Make: TOYOTA
Vehicle Model: HIACE HIGH ROOF COMMUTER TURBO AUTO
Primary Colour: White
Manufacturing Year: 2020
Engine No.: 1KDB069053
Chassis No.: JTFST22P300040327
Maximum Power Output: -
Open Market Value: \$54,204.00
Original Registration Date: 26 Mar 2021
First Registration Date: 26 Mar 2021
Transfer Count: 0
Actual ARF Paid: \$2,711.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 25 Mar 2031
COE Category: C - Goods Vehicle & Bus
COE Period(Years): 10
QP Paid: \$37,513.00
COE Rebate Amount: \$30,010.00
Total Rebate Amount: \$30,010.00

The information contained herein is correct as at 22 Jun 2022

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 18/06/2022 10:33 (SGT)
Date of Accident 17/06/2022 12:30 (SGT)
Exact Location of Accident Singapore
Additional Location Information 48 HOUGANG AVE 8 (THYE HE KWAN)
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number PC9606M

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner COMFORTDELGRO MEDCARE PTE LTD
Company Reg No 2XXXXX313K
Email Address jasminetan@cdgmedcare.com
Mobile Phone No (Phone) +65-96963798
Alternative Phone No (Office) +65-96963798

VEHICLE PARTICULARS

Manufacturer Toyota
Model HIACE HIGH ROOF COMMUTER TURBO AUTO
Variant -
Exact purpose for which vehicle was being used at time of accident Employment
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Commercial vehicle
Transmission Auto
CC 2982


INSURANCE COMPANY

Name of Insurance Company India International Insurance Pte Ltd
Type of Coverage Comprehensive
Fleet Policy No
Policy Number D22MFL0001917
Cover Note Number 21/01/22 - 20/01/23

DRIVER

Name of Driver CHNG KAH HOE
NRIC No SXXXX338A

Sketch Plan



48 Hougang Ave 8 (Thye He Kwan)

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DOA: 17/6/22 12:30pm

My vehicle hit onto beam when reversing.

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

(YS) 00 17/6/22
Reporting Centre Personnel's Signature
Name:

- Claim Own Policy Claim Third Party Reporting Only
 Claim OD/TP at other workshop (_____)