



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: ACS/105/009/2022/035

Date: 22nd July 2022

Our Ref: CS1/SPF22005989/Ucy3e2

M/s Automotive Engrg. & MGT. Division (TP)

Accident Claims Section

(Spore Police Force)

Police Logistics Base (PLB)

1 Hemmant Road

Singapore 438675

(The Motor Claims Department)

Attn: Hafizul Farhan

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLX 9284U

INSURED VEHICLE: QX 330U

ACCIDENT DATE: 02/03/2022

We thank you for your instruction on 23/06/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLX 9284U from M/s Kah Motor Co. Sdn. Bhd.
- b) Survey report by Tokio Marine Insurance Singapore Ltd with colour photographs.
- c) Final Repair Bill of SLX 9284U from M/s Kah Motor Co. Sdn. Bhd.
- d) Singapore Accident Statement and Police Report of Vehicles SLX 9284U.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLX 9284U
Make & Model	: Honda Jazz 1.3 CVT
Year of Registration	: 2018
Chassis Number	: JHMGK3850JX216890
Engine Capacity	: 1318 cc



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

2. Our finding is that the repair cost of \$4,353.77 (before GST) quoted by M/s Kah Motor Co. Sdn. Bhd is fair & reasonable.

3. We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.

Vehicle Inspected By:

CHUA KANG SENG
Licensed Appraiser

K.K.LAU
*MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust),MBA(UK),
IEng(UK), MIE(mech), MinstAEA, MFIEA,
MIRTE,MIMI,MSAE,MCIARD, AM,NIJAAR(USA),
AM CATARI(CAN),M.MATA(USA),M.MdATA(USA),
Licensed Appraiser*

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.