

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT
#01-49 SINGAPORE 415875
Tel: +65 64524457
Fax: +65 64524584
Company Reg No: 201929175W

Repair Estimate

Vehicle number: SLU3708U
Make & Model: Audi A6
Chassis number: WAUZZZ4G5CN104495

Date of survey:
Name of surveyor:
Contacts:

No.	Description of spare parts	Qty	Amount S\$
1	Bootlid <i>aluminum</i> 2300	1	\$ 3,789.00 <i>Ap 6 f</i>
2	Bootlid centre emblem 100	1	\$ 138.00 <i>nm</i>
3	Bootlid "A6" emblem 87	1	\$ 103.00 <i>nm</i>
4	Bootlid "2.0T" emblem	1	\$ 98.00 <i>nm</i>
5	Bootlid lock	1	\$ 278.00 <i>nm</i>
6	Bootlid lock catch	1	\$ 152.00 <i>nm</i>
7	Rear bumper 2058.54	1	\$ 2,519.00 <i>nm</i>
8	Rear bumper clips	1set	\$ 60.00 <i>nm</i>
9	Rear bumper lower spoiler 282.84	1	\$ 453.00 <i>nm</i>
10	Rear bumper reinforcement 774.40	1	\$ 872.00 <i>nm</i>
11	Rear bumper RH side reverse sensor	1	\$ 228.00 <i>nm</i>
12	Rear bumper RH centre reverse sensor 185	1	\$ 228.00 <i>nm</i>
13	Rear bumper LH centre reverse sensor 185	1	\$ 228.00 <i>nm</i>
14	Rear bumper LH side reverse sensor	1	\$ 228.00 <i>nm</i>
15	Rear bumper reverse sensor rubber seal	4	\$ 102.00 <i>nm</i>
16	Rear bumper reverse sensor holders	4	\$ 128.00 <i>nm</i>
17	Rear bumper towing cover	1	\$ 78.00 <i>nm</i>
18	Rear bumper RH side retainer	1	\$ 45.00 <i>nm</i>
19	Rear bumper RH lower bracket	1	\$ 22.00 <i>nm</i>
20	Rear bumper LH side retainer	1	\$ 45.00 <i>nm</i>
21	Rear bumper LH lower bracket	1	\$ 22.00 <i>nm</i>
22	Rear bumper centre bracket	1	\$ 292.00 <i>nm</i>
23	End panel	1	\$ 556.00 <i>nm</i>
24	End panel inner garnish	1	\$ 189.00 <i>nm</i>
25	End panel inner garnish clips	1set	\$ 40.00 <i>nm</i>
26	RH taillamp assy	1	\$ 1,181.00 <i>nm</i>
27	LH taillamp assy	1	\$ 1,181.00 <i>nm</i>
			\$ 13,255.00
			Parts less 5% \$ 662.75
			Total \$ 12,592.25

No.	Special Nett Items	Amount S\$
1	End panel joint sealant	\$ 70.00 <i>nm</i>

