

Huey Yon (LKKAuto)

From: Rasul (LKKAuto)
Sent: Monday, 26 September 2022 11:47 AM
To: SUR; CS A Team
Subject: FW: SMP 9373B

From: kenho@automotiverepaircentre.com.sg <kenho@automotiverepaircentre.com.sg>
Sent: Monday, 26 September 2022 11:46:49 am (UTC+08:00) Kuala Lumpur, Singapore
To: Rasul (LKKAuto) <Rasul@lkkauto.com>
Cc: Huey Yon (LKKAuto) <hueyyon@lkkauto.com>; 'ARC ShuJuan' <shujuan@automotiverepaircentre.com.sg>; raymond@automotiverepaircentre.com.sg <raymond@automotiverepaircentre.com.sg>
Subject: RE: SMP 9373B

Hi Derrick,

We confirmed COR amount at P/P \$15,138.69 and 12 work days.

Thank you.

Ken Ho
90219697
Automotive Repair Centre Pte Ltd
38 Woodlands Industrial Park E1
#05-18
Singapore 757700
Tel: +65 6468 8834
Fax: +65 6462 2278

From: Rasul (LKKAuto) <Rasul@lkkauto.com>
Sent: Monday, 26 September 2022 10:56 am
To: 'ARC Ken Ho' <kenho@automotiverepaircentre.com.sg>
Cc: Huey Yon (LKKAuto) <hueyyon@lkkauto.com>
Subject: SMP 9373B

Hi Ken,

refer to attachment

We will be advising our principal a cost of repair P/P \$15,138.69 /- with 12 days of repair, subject to their approval.

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.