

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte.
Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Hor, Yinrul

Date: 21 Jul 2022

Preliminary Advice

Vehicle No	: SLW1306Z	Accident Date	: 22/06/2022
Make	: AUDI A5	Policy No.	: 7220057330
Assignment Date	: 24/06/2022	Excess	: S\$0.00
Date of Inspection	: 23/06/2022	Est. Duration of Repair	: 16
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 62,768.00	(Estimate \$62,768.00 + Supplementary \$600.00)
Revised Amount	:S\$ 28,454.00	
Check Items (Estimated)	:S\$ 18,727.00	
Total	:S\$ 47,181.00	
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
-------------------	------

Pre-Accident Value	:S\$ 240,000.00
COE / PARF Rebate	:S\$ 127,800.00
Salvage Value	:S\$
Margin for Repair	:S\$ 112,200.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.