

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte.  
Ltd.  
AIG Building, 78 Shenton Way  
#09-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Rejab, Intan Syazatul Syima

Date: 24 Jun 2022

## **Preliminary Advice**

Vehicle No	: SLW1306Z	Accident Date	: 22/06/2022
Make	: AUDI A5	Policy No.	: 7220057330
Assignment Date	: 24/06/2022	Excess	: S\$0.00
Date of Inspection	: 23/06/2022	Est. Duration of Repair	: 13
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

## **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 62,168.00
Revised Amount	:S\$ 27,854.00
Check Items (Estimated)	:S\$ 18,727.00
Total	:S\$ 46,581.00
Lump Sum Repair	:S\$

## **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$ 240,000.00
COE / PARF Rebate	:S\$ 127,800.00
Salvage Value	:S\$
Margin for Repair	:S\$ 112,200.00

## **Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
  
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
  
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.