

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	22 Jun 2022 19:40	Clm Veh Model Changed		[] Merimen Administrator
2	22 Jun 2022 19:40	Clm Created	Reg No: SLW1306Z. Policy No: 7220057330. Acct Date: 2022/06/22. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:SPOR226M0002	[I] Merimen Administrator
3	24 Jun 2022 12:52	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] CELINE FONG
4	24 Jun 2022 12:52	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] CELINE FONG
5	24 Jun 2022 12:52	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CELINE FONG
6	24 Jun 2022 12:52	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2022/07/05	[A] CELINE FONG
7	24 Jun 2022 12:52	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] CELINE FONG
8	24 Jun 2022 12:52	Clm Registration Modified	Rep:1137->200611.	[A] CELINE FONG
9	24 Jun 2022 12:52	Clm Veh Model Changed	(205279) AUDI A5 2.0 SPORTBACK (A).	[A] CELINE FONG
10	24 Jun 2022 12:52	Adj Adjuster Assigned	[None] -> CHEN TSUE YEE	[A] CELINE FONG
11	24 Jun 2022 14:31	Adj Rpt Initiated		[A] Elaine Kuan Hwa Meen
12	24 Jun 2022 14:31	Clm Dtl Modified	Claim Conclusion: -> 3.	[A] Elaine Kuan Hwa Meen
13	24 Jun 2022 14:31	Clm Dtl Modified	JPJ Reg. Date: -> 2022/05/28.	[A] Elaine Kuan Hwa Meen
14	24 Jun 2022 14:31	Clm Details Notified		[A] Elaine Kuan Hwa Meen
15	24 Jun 2022 15:52	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2022/07/05	[A] SHIAU CHAN
16	24 Jun 2022 15:54	Adj Mandate Request	Cur.Req:46581.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN

AUDIT TRAIL

No.	On Audit	Remarks	By
17	24 Jun 2022 16:59 Cim Registration Modified	Init.Est.:->5,000 - 6,000. Excess: -> 0.00. Excess Waived: -> 1600.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Hor, Yinrul
18	24 Jun 2022 19:30 Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2022/07/05. Mandate Remarks: Vehicle may commence repair - Potential Recovery Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Pa	[I] Lim, Kok-Chong
19	24 Jun 2022 19:30 Adj Mandate Set	Approved:27854.00:Vehicle may commence repair - Potential Recovery Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair and docu	[I] Lim, Kok-Chong
20	21 Jul 2022 11:40 Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2022/07/05	[A] SHIAU CHAN
21	21 Jul 2022 11:41 Adj Mandate Request	Cur Req:47181.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. KINDLY APPROVE ON SUPPLEMENTARY.	[A] SHIAU CHAN
22	22 Jul 2022 09:26 Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2022/07/05. Mandate Remarks: *Potential Recovery * Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair	[I] Lim, Kok-Chong
23	22 Jul 2022 09:26 Adj Mandate Set	Approved:28454.00:*Potential Recovery* Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency. Before paint photos for all NEW Panels and Parts required after repair and document into Merimen.	[I] Lim, Kok-Chong

Date From  **Date To**  **Audit Type**

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2808599	24 Jun 2022 14:31:42	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLW1306Z		11.00