

**Note: This document has not been finalised.**

# **LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard  
#04-01 Suntec Tower Three  
Singapore 038988

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 29 Jun 2022

## **Preliminary Advice**

Vehicle No	: SJE9385K	Accident Date	: 22/06/2022
Make	: SKODA OCTAVIA	Policy No.	: DMPG21013795
Assignment Date	: 29/06/2022	Excess	: S\$0.00
Date of Inspection	: 28/06/2022	Est. Duration of Repair	: 8
Inspection At	: SKODA CENTRE SINGAPORE (HQ) 26 LENG KEE RD SINGAPORE 159104		

## **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,647.20
Revised Amount	:S\$	10,655.20
Check Items (Estimated)	:S\$	3,249.64
Total	:S\$	13,904.84
Lump Sum Repair	:S\$	

## **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	99,000.00
COE / PARF Rebate	:S\$	37,598.00
Salvage Value	:S\$	

Margin for Repair

:S\$ 61,402.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
  
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
  
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.