

Date: 24/06/2022

Vehicle No: SNC8928P

Model: TESLA MODEL 3 STANDARD RANGE

Chassis: LRW3F7FA9MC384625

Reg.Year: 2021

Third Party Insurer: LONPAC

Third Party Veh No: GBC197B

Date of Accident: 22/06/2022

Estimator: KIT

Surveyor:

*Not Authorised
Recovery Bk pay
4 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT	S\$	AMOUNT S\$
1	REAR BOOTLID	1			<i>Bu</i> \$728.97 ✓
2	REAR BOOTLID "TESLA" EMBLEM	1			<i>ma</i> \$37.38 ✓
3	REAR BOOTLID LAMP LH	1			<i>pu</i> \$177.57 X
4	REAR BOOTLID LAMP RH	1			<i>pu</i> \$177.57 X
5	REAR BOOTLID MECHANISM LOCK	1			<i>R</i> \$54.21 X
6	REAR BOOTLID INNER TRIM BOARD	1			<i>pu</i> \$345.79 X
7	REAR BOOTLID HINGE LH	1			SVC \$61.68 7X
8	REAR BOOTLID HINGE RH	1			SVC \$61.68 7X
9	REAR BOOTLID WEATHERSTRIP	1			Nec \$121.50 ✓
10	REAR TAIL LAMP LH	1			<i>pu</i> \$280.37 X
11	REAR TAIL LAMP RH	1			<i>pu</i> \$280.37 X
12	REAR TAIL LAMP BRACKET LH	1			<i>pu</i> \$2.80 X
13	REAR TAIL LAMP BRACKET RH	1			<i>pu</i> \$2.80 X
14	REAR BUMPER	1			<i>Bu</i> \$663.55 ✓
15	REAR BUMPER SIDE BRACKET LH	1		cra	<i>pu</i> \$7.48 ✓
16	REAR BUMPER SIDE BRACKET RH	1		cra	<i>pu</i> \$7.48 ✓
17	REAR BUMPER CENTER BRACKET	1		cra	\$52.34 ✓
18	REAR BUMPER LOWER LIP	1		Def	<i>pu</i> \$140.19 X✓
19	REAR BUMPER REFLECTOR LH	1			<i>pu</i> \$20.56 X
20	REAR BUMPER REFLECTOR RH	1			<i>pu</i> \$20.56 X
21	REAR BUMPER PARKING SENSOR	Shorted	2	\$158.88	\$317.76 71pc
22	REAR BUMPER PARKING SENSOR BRACKET	Nec	2	\$4.67	\$9.34 ✓
23	REAR BUMPER REINFORCEMENT	1			Def \$271.03 ✓
24	REAR END PANEL TOP GARNISH	1			<i>pu</i> \$299.07 X
25	REAR END PANEL	1			R REPAIR X
SUB TOTAL					\$4,142.05
LESS 10%					\$414.21
PARTS TOTAL					\$3,727.85

Date: 24/06/2022
Vehicle No: SNC8928P
Model: TESLA MODEL 3 STANDARD RANGE
Chassis: LRW3F7FA9MC384625
Reg.Year: 2021

Third Party Insurer: LONPAC
Third Party Veh No: GBC197B
Date of Accident: 22/06/2022
Estimator: KIT
Surveyor:

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BOOTLID INNER TRIM BOARD CLIPS	1		nn \$50.00
2	REAR BUMPER CLIPS	1		nn \$60.00
3	REAR NUMBER PLATE WITH HOLDER	1		nn \$50.00
			S/N TOTAL	\$160.00

X
✓
450

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS. \$800.00 400/

LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS. \$800.00 440/

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR. \$120.00 60/

TO REMOVE & REINSTALL REAR BOOTLID MECHANISM BACK TO ORIGINAL FUNCTIONS. \$100.00 60/

TO DAIGNOSIS FAULT CODE & RESET MEMORY. NN \$150.00 7X

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC. \$120.00 15/

TO TUFF KOTE & UNDERSEAL MATERIALS. nn \$100.00 X

LABOUR TOTAL \$2,190.00

KIT TOTAL \$6,077.85