



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile CS3/LPC22005037/Eqy3-1

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: ~~CS3/LPC22005037/eqy3-1~~

Date: ~~27/05/2022~~ 23/06/2022

Code: LPC2

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	GBA 5219A	Veh. Inspected	SKT 3771C
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	27/05/2022 23/06/2022

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	26/05/2022	Inspection Date	
Survey held at	TRINICE AUTOMOBILE SERVICES BLK 1001 BUKIT MERAH LANE 3 #01-63 SINGAPORE 159724		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.