

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	LONPAC INSURAN	ICE BHD		Ref:	CS3/LPC22001117/Gny3e2-1	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555		Date:	26/07/2022	
				Code:	LPC2	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	GW 4283U	Veh. Inspected		SKZ 2223T	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	22/22/22/VC05/025429	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		24/06/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA VEZEL	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	RU11105730	Colour		BLUE	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	215/55Z R17	HABILEAD		6 mm	
	L/H Front Tyre	215/55Z R17	HABILEAD		6 mm	
	R/H Rear Tyre	215/55Z R17	HABILEAD		6 mm	
	L/H Rear Tyre	215/55Z R17	HABILEAD		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	30/01/2022	Inspection Dat	е	07/02/2022	
	Survey held at	290 MacPherson road				
	Repairer	TT MOTORSPORT PTE LTD				
5a.	a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 10 Working Days				