

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : ~~SHE 259K~~ SHD 3259K

Make : HYUNDAI

Model : I-40

Date: 07/06/2022

Insurance: NTUC

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRT BUMPER COVER			\$ 1,052.20
10	FRT BUMPER CLIPS			\$ 22.00
1	RADIATOR GRILLE			\$ 1,480.00
1	FRT BUMPER CENTRE GRILLE			\$ 114.00
	SUB TOTAL		2554.20	\$ 2,668.20
	LESS 20% DISCOUNTED TOTAL		2043.36	\$ 2,134.56
	FRT NUMBER PLATE WITH TRIM COVER		55	\$ 55.00
				\$ 55.00
	Labour Charge			
	CHL ALL LIGHTING			\$ 60.00
	PANEL BEATING		530	\$ 300.00
	SPRAY PAINTING CHARGE			\$ 300.00
	TOTAL LABOUR		2628.36	\$ 660.00
	ESTIMATE TOTAL		4671.72	\$ 2,849.56

de
hel
an
Kun.

an

Kun.
280
250

* 2 days

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 97445749
WP' 7/6/22 C315p
- 2 days
4/5 hour after repair
Tanpin ellhantok.u

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Sign: ..