## COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

LKK-Taufikh.

DATE:

14.06.2022

MODEL:

Toyota Prius

VEHICLE NO.: SH 8308T

INSURANCE: NTUC (45)

MVA: LIM T S

| PART NO. | DESCRIPTION  | QTY | UNIT PRICE | AMOUNT  |
|----------|--|-----|------------|---|
|          | Rear Bumper  | 1   |            | \$503.04                                      |
|          | Rear Bumper Re-Inforcement                         | 1   | 1          | \$378.32 2 nn                                 |
|          | Rear Bumper Lower Cover-Black                      | 1   |            | \$654.96 ~                                    |
|          | Rear Bumper Tow Cover                              | 1   |            | \$82.70 de                                    |
|          | Rear Bumper Clips                                  | 10  | \$2.20     | \$22.00                                       |
|          | SUB TOTAL  |     |            | \$1,641.02 759.                               |
|          | LESS 25%   |     |            | \$410.25                                      |
|          | DISCOUNTED TOTAL                                   |     |            | \$1,230.76                                    |
|          | Reverse Sensor                                     | 1   |            | \$135.70 Xnn                                  |
|          | SUB S/NETT   |     |            | \$135.70                                      |
|          | LESS 10%   |     |            | \$13.57                                       |
|          | SUB S/NETT TOTAL                                   |     |            | \$122.13                                      |
|          | Rear Bumper Adv.Sticker                            | 1   | ı          | \$100.00 NETT 106                             |
|          | Rear Fender Adv.Sticker RH/LH                      | 2   | \$100.00   | \$200.00 NETT Jee                             |
| 1        | TOTAL SPARE PARTS                                  |     | -          | \$1,652.89                                    |
|          | Labour Charge                                      |     |            |   |
| 1        | Panel Beating                                      |     |            | \$400.00 \$50                                 |
|          | Spray Painting Charge                              |     |            | \$300.00 750                                  |
|          | Remove/Refix Reverse Sensor                        |     |            | 4000.00                                       |
| ľ        | terre veri terre e e e e e e e e e e e e e e e e e |     |            | \$120.00                                      |
|          | TOTAL LABOUR                                       |     |            | \$820.00 630<br>\$2,472.89 14 99 7<br>4/5\$12 |
|          | ESTIMATE TOTAL                                     |     |            | \$2,472.89 14 99                              |
|          | ATT 1  |     | 1          | , , , , ,                                     |

the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanfle 9749579 WP H/2/2701/50 «Zolnys L/3 Nesny Ater regaring tempile & Unhange an

LKK Auto Consultants hence notify

- the Repairer of the following: To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: