

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

205 Braddell Road
Singapore 579701

Tel: 63837613 Fax: 62815767/65462533 Email: teokeejin@cdge.com.sg

INSURER: India International Insurance Pte Ltd (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	D18MFL0003414-02	Date of Loss:	23/06/2022
Vehicle Reg. No.:	SND5080Z	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	COMFORTDELGRO RENT-A-CAR PTE LTD		

Make/Model:	TOYOTA SIENTA HYBRID, 1.5 X CVT (A)	Vehicle Reg. Date:	05/01/2022
Vehicle Colour:	BLUE	Chassis No:	NHP1707251348
Engine No:	1NZ9329578		
Odometer:	0 KM		

Paint Type:
Total Loss? NO

Est. Duration of Repair (day)

3 days

*Not Authorised
Repair Beyond
EX TBA*

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)

COST OF CLAIMS	Amount
Parts	2,522.31
Miscellaneous Items	11.00
Labour	1,430.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	3,963.31
+ GST 7.00% (S\$)	277.43
Nett Amount (S\$)	4,240.74

This claim is handled by: PATRICK TIA JEE KIANG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Jun 2022)

Parts: M1-MPV TOYOTA SIENTA HYBRID 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SND5080Z/27/06/2022 09:52

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT NUMBER PLATE W/CASE	CM 0	0.00	*45.00 FS	✓
2	1		*FRT BUMPER	CM 25	0.00	*390.00 F	✓
3	8		*FRT BUMPER CLIP	CM 25	0.00	*45.68 F	✓
4	1		*FRT BUMPER RH SIDE RETAINER	DI 25	0.00	*65.20 F	✓
5	1		*FRT BUMPER LH SIDE RETAINER	DI 25	0.00	*65.20 F	X
6	1		*RADIATOR GRILLE ASSY	CM 25	0.00	*830.00 F	✓
7	1		*FRT LOGO	DI 25	0.00	*72.00 F	✓
8	1		*FRT BUMPER TOW COVER RH	DI 25	0.00	*46.00 F	✓
9	1		*FRT BUMPER TOP RUBBER SEAL	DI 25	0.00	*40.00 F	✓
10	1		*FRT BUMPER SPONGE	25	0.00	*103.00 F	?
11	1		*FRT BUMPER INFORCEMENT	25	0.00	*397.00 F	?
12	1		*FRT BUMPER TOP BEAM	25	0.00	*116.00 F	?
13	1		*RH HREADLAMP	DI 25	0.00	*1,020.00 F	✓
14	1		*FRT BUMPER LOWER CENTER GRILLE SIDE COVER	DI 25	0.00	*113.00 F	X

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	3,348.08
- List Item Discount on L Items (\$\$)	825.77
Total Parts (\$\$)	2,522.31

ComfortDelGro Engineering Pte Ltd/SND5080Z/27/06/2022 09:52. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey ~~before~~ after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Miscellaneous Items
 Miscellaneous Items
 OD/TP Case (Insurer)

Amount

11.00

Sub Total (S\$)

11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	TO PANEL BEAT ON FRONT PANEL ,RH FENDER,REPLACE DAMAGE PARTS AND REALIGN AFFECTED AREAS	New	600.00	300
2	TO PUTTY,RESPRAY ON FRT BUMPER ,FRT PANEL,RH FRT FENDER AND AFFECTED AREAS	New	800.00	250
3	CHECK LIGHTING AND WIRING	New	30.00	20
Gross Labour Cost (S\$)			1,430.00	

ComfortDelGro Engineering Pte Ltd/SND5080Z/27/06/2022 09:52. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >