9/1/22, 5:20 PM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/GRB22006113/VVY3Q2

01/09/2022 Date:

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447\_01

**Claimant Vehicle** FBN3181T Insured Vehicle No: SLP8953X

No:

Date of Loss: 02/06/2022 Nature of Claim: TP Claim No: MFL2022D0003370

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **FBN3181T** 

Make & Model: HONDA VARIO, 149cc Engine No: KF41E1104964

Reg. Date: 08/09/2018 (Man. Year: 2018) Chassis No: MH1KF4113JK104312

Colour: Odometer: Grey 0 km

**Engine Capacity:** 149 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes No

CONDITION OF TYRES

Front Tyre Size: 90/90-14 Rear Tyre Size: 90/90-14

Front Left Side: Rear Left Side: Bridgestone 5 mm Bridgestone 5 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,490.00	1,341.00	149.00	10.00
Miscellaneous Items		0.00	0.00	0.00	
Labour		380.00	260.00	120.00	31.58
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	1,870.00	1,601.00	269.00	14.39
	Approved Total (Overridden) (S\$)		1,300.00		
	Nett Amount (S\$)	1,870.00	1,300.00	570.00	30.48

**INSPECTION** 

Date Inspected:

Date of Assignment: 27/06/2022

> First Motor (HQ) 27/06/2022 Inspected At:

Blk 3006 #01-398, Ubi Road 1

Singapore 408700

Estimated Period of Repair: 4.0 days

Manager: **VERON CHEN** Adjuster: Thevan Thomas Karthikesavan

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

9/1/22, 5:20 PM Adjuster Report

### **REPAIR DETAILS**

Reference

Part Source: (Last Synchronised: 31 Aug 2022)

Parts: N/A HONDA VARIO 149cc (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for FBN3181T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BRAKE LEVER	Scratched	20.00 F	*20.00 FL
2	1		*MIRROR	Scratched	30.00 F	*30.00 FL
3	1		*FRONT COVER PANEL	Scratched	45.00 F	*45.00 FL
4	1		*TOP SIDE COVER (R)	Scratched	80.00 F	*80.00 FL
5	1		*TOP SIDE COVER (R)	Scratched	55.00 F	*55.00 FL
6	1		*FLOOR BOARD COVER OUTER	Scratched	90.00 F	*90.00 FL
7	1		*LOWER (R) SIDE COVER	Scratched	110.00 F	*110.00 FL
8	1		*FRONT MUDGUARD	Scratched	70.00 F	*70.00 FL
9	1		*FORK ASSY	Bent	380.00 F	*380.00 FL
10	1		*FRONT WHEEL	Bent	220.00 F	*220.00 FL
11	1		*REAR FOOT REST (R)	Scratched	35.00 F	*35.00 FL
12	1		*EXHAUST PIPE PROTECTOR	Scratched	45.00 F	*45.00 FL
13	1		*REAR SIDE COVER (R)	Scratched	130.00 F	*130.00 FL
14	1		*REAR NUMBER PLATE	Scratched	20.00 F	*20.00 FL
15	1		*REAR GIVI BOX	Scratched	160.00 F	*160.00 FL
F=Fra	anchise	part. L=ListIten	nDisc.			
				Sub Total (S\$)	1,490.00	1,490.00
			- List Item Discount on L Items 0.00/10.00% (S\$)		0.00	149.00
				Total Parts (S\$)	1,490.00	1,341.00

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TOWING SERVICE	New	80.00	60.00
2	WORKMANSHIP STRIP & FIX BODY PARTS	New	300.00	200.00
		Gross Labour Cost (S\$)	380.00	260.00
	Report was un	submitted during this print-out.		

< END OF ESTIMATES >