

## Vehicle Damage Assessment Report for [SMH81U]

Estimate Created: 27/06/2022 15:05 by LKK\_admin-a  
(LKK\_Auto\_Consultants\_Pte\_Ltd)

Owned: 06/04/2023 09:41 by LKK\_cs-a (LKK\_Auto\_Consultants\_Pte\_Ltd)

### General Information

Insurance Company		Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

### Vehicle Information

Brand	Porsche	Model	Macan
Engine Type			
License Plate Number	SMH81U	VIN (or Chassis #)	

### Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

### Comments

- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK:  
CONCLUDED THE COST OF REPAIR AT \$11,543.10 WITH 5 WORKING DAYS

Insurlogic 5 (06/04/2023 09:41)

**Parts**

Description	Number/Type	Qty	Cost	Markup/Disc. %	Sum
SENSOR GASKET		1	13.20	0.00 %	13.20
WHEEL COVER FLAP LH		1	50.90	0.00 %	50.90
EXPANSION RIVET		1	4.80	0.00 %	4.80
EXPANDER NUT		1	9.20	0.00 %	9.20
REAR DOOR LOWER TRIM GARNISH		1	586.70	0.00 %	586.70
REPAIR KIT		1	113.10	0.00 %	113.10
ALLOY WHEEL TITANIUM		1	4305.20	0.00 %	4,305.20

Parts Subtotal 5,083.10

**Labor****Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
TO REMOVE /REPLACE REAR BUMPER, REAR DOOR LH & ALL ACCIDENT DAMAGED BODY PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	RnR	2340.00	0.00 %	2,340.00
TO MOUNT 1 PC SPORT RIM AND CONDUCT WHEEL BALANCING.	RnR	120.00	0.00 %	120.00
TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT	RnR	680.00	0.00 %	680.00
TO TRANSFER THE REVERSE SENSORS.	RnR	150.00	0.00 %	150.00
TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	RnR	150.00	0.00 %	150.00
TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	RnR	600.00	0.00 %	600.00
SUNDRIES	RnR	20.00	0.00 %	20.00

**Paint**

Description	Paint Type	Cost	Markup/Disc %	Price
TO RESPRAY REAR BUMPER, REAR DOOR LH .	Full spray	2400.00	0.00 %	2,400.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 4,060.00

Paint Labor Subtotal 2,400.00

Labor Subtotal 6,460.00

**Summary**

Repair Cost 11,543.10

Discount(0 %)	(0.00)
	11,543.10
Excess	(0.00)
GST(0.00 %)	0.00
<hr/>	
Grand Subtotal	11,543.10