

INDIA INT'L INSURANCE PTE LTD		NAME :		WIP : 32399	
64 CECIL STREET #04-05		ADDRESS :		EXCESS :	
IOB BUILDING				DATE: 25-Jun-22	
SINGAPORE 049711		TEL :			
ATTN. : MOTOR CLAIMS					
FAX :					
VEH NO :	SMH81U	DATE IN :		CONTACT PERSON :	JOB: 63310682
CHASSIS NO :	WP1ZZZ95ZKL21026	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY
MODEL :	Macan S	DATE REG.:	23-Aug-19	POLICY NO. :	

NATURE OF WORKS

S/NO	Parts Description	QTY	1ST	SUPP	REVISED	PRICES
1	REAR BUMPER <i>X R</i>	1				\$ 1,155.80
2	SEOR GASKET <i>/ MC</i>	4				\$ 13.20
3	WHEEL COVER FLAP LH <i>/ RWT</i>	1				\$ 50.90
4	EXPANSION RIVET <i>/ MC</i>	8				\$ 4.80
5	EXPANDER NUT <i>/ MC</i>	4				\$ 9.20
6	REAR DOOR LH <i>X R</i>	1				\$ 2,203.40
7	DOOR CHECKER <i>X nn</i>	1				\$ 113.40
8	HEXAGON SOCKET HEAD BOLT <i>X nn</i>	2				\$ 3.80
9	COMBINATION SCREW <i>X nn</i>	1				\$ 2.50
10	DOOR SEAL OUTER LH <i>X nn</i>	1				\$ 248.60
11	DOOR SEAL C-PILLAR <i>X nn</i>	1				\$ 190.80
12	GASKET <i>X nn</i>	4				\$ 5.20
13	STOPPER <i>X nn</i>	2				\$ 14.80
14	INSULATION <i>X nn</i>	1				\$ 10.90
15	CLIP <i>X nn</i>	6				\$ 6.60
16	P958-537-437-40-/(WH17) ADHESIVE TAPE DO <i>X nn</i>	1				\$ 132.40
17	COMBINATION SCREW (WH03) <i>X nn</i>	2				\$ 6.20
18	SCREW <i>X nn</i>	6				\$ 7.80
19	CAVITY PRESERVATION (AKA3) <i>X nn</i>	1				\$ 72.40
20	P000-043-207-67-/SEALANT (W736) <i>X nn</i>	1				\$ 67.20
21	REAR DOOR LOWER TRIM GARNISH <i>X / MC</i>	1 <i>(phth)</i>				\$ 586.70
22	REPAIR KIT <i>X / MC</i>	1				\$ 113.10
23	ALLOY WHEEL TITANIUM <i>/ MC</i>	1				\$ 4,305.20
24		0				\$ -
TOTAL PARTS						\$ 9,324.90
						\$ -
TOTAL PARTS COST						\$ 9,324.90

SUPPLEMENTARY

NO	DESCRIPTION	QTY	PARTS NO	1st	Supp	REVISED	PRICES
1							
2							
3							

Labour Description					
	TO REMOVE /REPLACE REAR BUMPER, REAR DOOR LH & ALL ACCIDENT DAMAGED BODY PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	1560 x 1.5	2340 ✓	\$	4,680.00
2	TO RESPRAY REAR BUMPER, REAR DOOR LH.	1700 1100	2400 ✓	\$	2,600.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION.			\$	250.00 X
4	TO MOUNT 1 PC SPORT RIM AND CONDUCT WHEEL BALANCING.		NETT	\$	120.00 ✓
5	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.		NETT	\$	680.00 ✓
6	TO TRANSFER THE REAR DOOR LH MECHANISM.		NETT	\$	780.00 X
7	TO INSTALL THE BODY WRAP PROTECTION STICKER. (PRICE TO BE ADVISE) (quote and invoice)		NETT		8 X
8	TO TRANSFER THE REVERSE SENSORS.			\$	300.00 150
9	TO APPLY SPECIAL CERAMIC COATING. (PRICE TO BE ADVISE) (quote and invoice)		NETT		8 X
10	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			\$	250.00 150
11	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		NETT	\$	600.00 ✓
12	SUNDRIES.		NETT	\$	50.00 20

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TOTAL LABOUR	\$	-	\$	10,310.00
TOTAL PARTS	\$	-	\$	9,324.90
TOTAL	\$	-	\$	19,634.90
LESS EXCESS	\$	-	\$	-
TOTAL AFTER EXCESS	\$	-	\$	19,634.90
GST 7%	\$	-	\$	1,374.44
GRAND TOTAL	\$	-	\$	21,009.34

EUROKARS AUTO PTE LTD

Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: