

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29

Kaki Bukit Autohub. Singapore 417921

Tel No. : 67461515 / 67471787 Fax No. : 67485015

Website : www.successunited.com.sg

Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd

AIG Building

78 Shenton Way, #07-16

Singapore 079120

Attention : Motor Claim Department

Contact : 64191053 Fax No. : 68357416

Estimate : TP22-069

Date : 24/06/2022

Vehicle Num. : SMR9277K

Make/Model : M/Benz GLC250-2018

Chassis/Eng# : WDC2533462F494803/27492031590069

Accident Date : 23/06/2022

Claim No. :

Reference :

Policy No. : (30/01/2023)

Xiao Tony

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1 pc	Bonnet <i>Dented.</i>		2,450.00 <i>2343</i>
2.	2 pcs	Bonnet Hinge L/R <i>new</i>	284.00	568.00 <i>x</i>
3.	2 pcs	Bonnet Damper L/R <i>new</i>	158.00	316.00 <i>x</i>
4.	1 pc	Bonnet Weatherstrip <i>new</i>		92.00 <i>x</i>
5.	1 pc	Bonnet Mechanism Lock <i>new</i>		132.00 <i>x</i>
6.	1 pc	Bonnet Top Hook Lock <i>new</i>		65.00 <i>x</i>
7.	2 pcs	Headlamp Assy L/R <i>crushed</i>	3,534.00	7,068.00 <i>x</i>
8.	1 pc	Headlamp Bracket LH <i>new</i>		78.00 <i>x</i>
9.	1 pc	Frt Bumper Assy <i>Debond</i>		2,270.00 <i>1915</i>
10.	10 pcs	Frt Bumper Clips <i>new</i>	9.50	95.00 <i>30</i>
11.	2 pcs	Frt Bumper Bracket L/R <i>Dented</i>	54.30	108.60 <i>x</i>
12.	2 pcs	Frt Bumper Side Holder L/R <i>new</i>	92.00	184.00 <i>x</i>
13.	1 pc	Frt Bumper Inner Base Frame <i>new</i>		297.00 <i>x</i>
14.	1 pc	Frt Bumper Tow Hook Cover <i>new</i>		105.00 <i>x</i>
15.	2 pcs	Frt Bumper Parking Sensor <i>new</i>	240.00	480.00 <i>x</i>
16.	1 pc	Frt Bumper Inner Sponge <i>crushed</i>		255.00 <i>x</i>
17.	1 pc	Frt Bumper Reinforcement <i>Best</i>		595.00 <i>x</i>
18.	1 pc	Frt Bumper Reinforcement Bracket <i>Best</i>		296.00 <i>x</i>
19.	1 pc	Frt Bumper Lower Air Grille <i>crushed</i>		190.00 <i>x</i>
20.	1 pc	Frt Bumper Lower Extension <i>new</i>		210.00 <i>x</i>
21.	1 pc	Frt Bumper Lower Guard LH <i>new</i>		105.00 <i>x</i>
22.	1 pc	Frt Bumper Lower Guard Cover Trim LH <i>missing</i>		272.00 <i>x</i>
23.	1 pc	Frt Foglamp Cover LH <i>Debond</i>		130.00 <i>x</i>
24.	1 pc	Frt Grille Assy <i>crushed</i>		1,348.00 <i>180</i>
25.	1 pc	Frt Grille 'Mercedes' Logo <i>new</i>		320.00 <i>350</i>
26.	1 pc	Frt Grille Chrome Trim <i>new</i>		518.00 <i>x</i>
27.	1 pc	Frt Grille Bracket <i>new</i>		92.00 <i>x</i>
28.	2 pcs	Radiator Side Air Guide L/R <i>new</i>	102.00	204.00 <i>102</i>
29.	1 pc	Frt No. Plate Base <i>Debond</i>		155.00 <i>x</i>

List Total S\$:

10.00% Discount S\$:

15567.60

14010.84

18,998.60

1,899.86

17,098.74

CONTINUE / ...

SUCCESS UNITED PTE LTD

2 Kaki Bukit Ave 2, #01-33 / #02-29
Kaki Bukit Autohub. Singapore 417921
Tel No. : 67461515 / 67471787 Fax No. : 67485015
Website : www.successunited.com.sg
Buss. Reg. No. : GST No. 200402570G

AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way, #07-16
Singapore 079120

Attention : Motor Claim Department
Contact : 64191053 Fax No. : 68357416

Estimate : TP22-069

Date : 24/06/2022
Vehicle Num. : SMR9277K
Make/Model : M/Benz GLC250-2018
Chassis/Eng# : WDC2533462F494803/27492031590069
Accident Date : 23/06/2022
Claim No. :
Reference :
Policy No. : (30/01/2023)

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1 set	SPECIAL NETT ITEMS : Frt No. Plate w/Frame <i>Damaged</i>	<i>45</i>	45.00 ✓
		Special Nett Total S\$:		45.00
		LABOUR :		
		To remove, rearrange electrical wirings, check lighting		80.00 ✓ <i>30</i>
		To remove, repair and replaced damaged bodyparts, realign bodyworks & where consistent to the accident	<i>1080</i>	650.00 ✓ <i>530</i>
		To putty and respray painting on affected area.		800.00 ✓ <i>50</i>
		Labour Total S\$:		1,530.00

Admin Lg
L/s 27/06/22
05 Days.

Total S\$: 18,673.74

=====

Total: 15135.84
L/s: 12-1 K

SUCCESS UNITED PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: