

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Allianz Insurance Singapore Pte.
Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Lim

Date: 06 Jul 2022

Preliminary Advice

Vehicle No	: SKC7177G	Accident Date	: 26/06/2022
Make	: TOYOTA CAMRY	Policy No.	: SP2001891658
Assignment Date	: 28/06/2022	Excess	: S\$600.00
Date of Inspection	: 28/06/2022	Est. Duration of Repair	: 10
Inspection At	: BORNEO MOTORS (S) PTE LTD (PANDAN) 2 PANDAN CRESCENT SINGAPORE 128462		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 45,636.70	(Estimate \$45,265.00 + Supplementary \$371.70)
Revised Amount	:S\$ 26,149.80	
Check Items (Estimated)	:S\$ 16,504.90	
Total	:S\$ 42,654.70	
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
-------------------	------

Pre-Accident Value	:S\$ 123,000.00
COE / PARF Rebate	:S\$ 57,336.00
Salvage Value	:S\$
Margin for Repair	:S\$ 65,664.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.