

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 12 July 2022 3:24 PM
To: Thomas.Pang@borneomotors.com.sg
Cc: SUR
Subject: RE: ALLIANZ-OD SKC 7177G DOA: 26/06/2022
Attachments: SKC 7177 supp.pdf

Dear Thomas,

Please proceed the supplementary as attached with our surveyor marking.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Tuesday, 28 June 2022 6:57 PM
To: Thomas.Pang@borneomotors.com.sg
Cc: SUR <sur@lkkauto.com>
Subject: ALLIANZ-OD SKC 7177G DOA: 26/06/2022

Dear Thomas,

As instructed by our client, please proceed to repair the insured vehicle **SKC 7177G (Excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)