



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no : 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
Allianz Insurance Singapore Pte Ltd 12 Marina View #14-01 Asia Square Tower 2 Singapore 018961			S1000040 / ALLIANZ		Mrs Grace Yap Mui Huang 681B Jurong West Central 1 #14-72 Singapore 642681 Mobile: 92302911		
			Document No. 0				
			Document Date 27/06/2022				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	AXVA70R	JEZGBT E1	17/06/2019	SKC7177G	0	15995	72/OD/SKC7177G
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MR2B63HK504001631		A25A0331527	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES POLICY NO.: SP2001891658 ACC DATE: 27.06.2022 TOW IN: 26.06.2022 EXCESS: DATE-IN: 26.06.2022 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				50	100.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)					200.00
3	B	BP-LAB2 REPLACE AND REFOCUS HEADLAMP					122.40
4	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR					180.00
5	B	BP-LAB2 TO RESET ECU AND REPROGRAMME					180.00
6	B	BP-LAB2 TO CONDUCT ADJUSTMENT ON FRONT RADAR SENSORS					180.00
7	S	BP-SUBLET R/I AC CONDENSOR, PIPING AND REGAS					360.00
8	L	BP-LPO SUPPLY REGN PLATE (PO#)					80.00
9	B	BP-LAB2 REPLACE ACC DAMAGED PARTS 770 X 5 AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS				3600	4320.00
10	B	BP-RES2 RESPRAY ACC AFFECTED AREAS 590 X 5				2950	4130.00
11	1	S52119-0X951 COVER, FR BUMPER, L/	1.00	581.40			581.40
12	2	S53395-06110 SEAL, HOOD TO FR END 1	1.00	71.90			71.90
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Customer Copy

**Borneo Motors**

Inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

No 2 PANDAN CRESCENT

SINGAPORE 128462, Tel no : 6631 1188

**TOYOTA****ESTIMATE**

Account Details		Account No.	Customer Details	
Allianz Insurance Singapore Pte Ltd 12 Marina View #14-01 Asia Square Tower 2 Singapore 018961		S1000040 / ALLIANZ	Mrs Grace Yap Mui Huang	
		Document No. 0	681B Jurong West Central 1 #14-72 Singapore 642681	
		Document Date 27/06/2022	Mobile: 92302911	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	AXVA70R	JEZGBT E1	17/06/2019	SKC7177G	0	15995	72/OD/SKC7177G

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
MR2B63HK504001631	A25A0331527	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
13	3	S52114-06460 BRACKET, FR BUMPER E <i>(Caulk plus hole) - OR</i>	1.00	108.70		108.70
14	4	S53102-06510 GRILLE SUB-ASSY, RAD <i>- OR (Bump)</i>	1.00	599.80		599.80
15	5	S53128-06080 GRILLE, RADIATOR, LW <i>- OR</i>	1.00	30.50		30.50
16	6	S52422-06060 PAD, FR BUMPER, RH <i>- OR</i>	1.00	17.60		17.60
17	7	S52423-06060 PAD, FR BUMPER, LH <i>- OR</i>	1.00	17.60		17.60
18	8	S52535-06240 RETAINER, FR BUMPER <i>?</i>	1.00	93.70		93.70
19	9	S52536-06240 RETAINER, FR BUMPER <i>?</i>	1.00	93.70		93.70
20	0	S52611-06490 ABSORBER, FR BUMPER <i>- OR ?</i>	1.00	111.30		111.30
21	1	S52131-06210 REINFORCEMENT, FR BU <i>- BT</i>	1.00	387.00		387.00
22	2	S52618-06070 ABSORBER, FR BUMPER, <i>- OR</i>	1.00	200.50		200.50
23	3	T90467-05170 CLIP <i>- OR</i>	2.00	2.80		5.60
24	4	T47749-33030 CLIP, PIN HOLD <i>- OR</i>	4.00	9.50		38.00
25	5	T53879-33030 RETAINER, FR FENDER <i>?</i>	4.00	13.20		52.80
26	6	S53101-06C30 GRILLE SUB-ASSY, RAD <i>- OR</i>	1.00	418.20		418.20
27	7	S53123-06170 MOULDING, RADIATOR G <i>- OR</i>	1.00	66.20		66.20
28	8	S53124-06170 MOULDING, RADIATOR G <i>- OR</i>	1.00	66.20		66.20
29	9	S88210-06150 SENSOR ASSY, MILLIME <i>?</i>	1.00	2082.90		2082.90
30	0	S53301-06360 HOOD SUB-ASSY <i>- OR</i>	1.00	1766.00		1766.00
31	1	S53381-06230 SEAL, HOOD TO RADIAT <i>?</i>	1.00	57.50		57.50
32	2	S53341-06500 INSULATOR, HOOD <i>- CR4</i>	1.00	649.10		649.10

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy

**Borneo Motors**

Inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

No. 2 PANDAN CRESCENT

SINGAPORE 128462, Tel no. 6631 1188

**TOYOTA****ESTIMATE**

Account Details		Account No.	Customer Details					
Allianz Insurance Singapore Pte Ltd 12 Marina View #14-01 Asia Square Tower 2 Singapore 018961		S1000040 / ALLIANZ	Mrs Grace Yap Mui Huang 681B Jurong West Central 1 #14-72 Singapore 642681 Mobile: 92302911					
		Document No. 0						
		Document Date 27/06/2022						
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	AXVA70R	JEZGBT E1	17/06/2019	SKC7177G	0	15995	72/OD/SKC7177G	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MR2B63HK504001631		A25A0331527	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
33	3	T90467-09050 CLIP / MC			10.00	3.10		31.00
34	4	S53802-06210 FENDER SUB-ASSY, FR (LH) - M			1.00	933.00		933.00
35	5	S53510-06370 LOCK ASSY, HOOD			1.00	146.80		146.80
36	6	S53410-06460 HINGE ASSY, HOOD, RH - BT			1.00	63.70		63.70
37	7	S53420-06460 HINGE ASSY, HOOD, LH - BT			1.00	63.70		63.70
38	8	T90469-06005 CLAMP			3.00	4.20		12.60
39	9	S53630-06271 CABLE ASSY, HOOD LOC			1.00	59.40		59.40
40	0	S53481-06170 BRACKET, HOOD SUPPORT			1.00	11.40		11.40
41	1	S53205-06250 SUPPORT SUB-ASSY, RA			1.00	371.40		371.40
42	2	S52081-06030 STAY SUB-ASSY, FR BU			2.00	41.60		83.20
43	3	S53202-06260 SUPPORT SUB-ASSY, RA			1.00	265.10		265.10
44	4	S53203-06300 SUPPORT SUB-ASSY, RA			1.00	265.10		265.10
45	5	S57104-06090 MEMBER SUB-ASSY, FR			1.00	245.30		245.30
46	6	S53253-06020 BRACKET, RADIATOR MO			2.00	65.00		130.00
47	7	S16594-F0030 GUIDE, RADIATOR AIR,			1.00	48.70		48.70
48	8	S16593-F0080 GUIDE, RADIATOR AIR,			1.00	98.30		98.30
49	9	S16595-F0080 GUIDE, RADIATOR AIR,			1.00	90.40		90.40
50	0	S16592-F0030 GUIDE, RADIATOR AIR,			1.00	59.20		59.20
51	1	S16691-F0070 PLATE, RADIATOR SIDE			1.00	40.20		40.20
52	2	S16695-F0070 PLATE, RADIATOR SIDE			1.00	38.30		38.30
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts		Less		
				Labour				
				Sublet				
				Lubrication/Fluid				
				Others		Amount Due		

Customer Copy

**Borneo Motors**

Inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-850000-9

No. 2 PANDAN CRESCENT

SINGAPORE 128462, Tel no : 6631 1188

**TOYOTA****ESTIMATE**

Account Details		Account No.	Customer Details					
Allianz Insurance Singapore Pte Ltd 12 Marina View #14-01 Asia Square Tower 2 Singapore 018961		S1000040 / ALLIANZ	Mrs Grace Yap Mui Huang 681B Jurong West Central 1 #14-72 Singapore 642681 Mobile: 92302911					
		Document No. 0						
		Document Date 27/06/2022						
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	AXVA70R	JEZGBT E1	17/06/2019	SKC7177G	0	15995	72/OD/SKC7177G	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
MR2B63HK504001631		A25A0331527	60	Thomas Pang W T	--/--/----	0.00	--/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
53	3	S53295-06230	SEAL, COOL AIR INTAK	1.00	212.20		212.20	
54	4	T90467-07217	CLIP	10.00	2.80		28.00	
55	5	S57013-06030	BRACKET SUB-ASSY, FR	1.00	338.00		338.00	
56	6	S57014-06040	BRACKET SUB-ASSY, FR	1.00	338.00		338.00	
57	7	S55708-06330	LOUVER SUB-ASSY, COW	1.00	699.00		699.00	
58	8	S53866-06170	SEAL, FR FENDER TO C	1.00	49.70		49.70	
59	9	S53867-06170	SEAL, FR FENDER TO C	1.00	49.70		49.70	
60	0	S81110-06E80	HEADLAMP ASSY, RH	1.00	4730.30		4730.30	
61	1	S81150-06E80	HEADLAMP ASSY, LH	1.00	4730.30		4730.30	
62	2	T81210-48051	LAMP ASSY, FOG	1.00	516.00		516.00	
63	3	T81220-48051	LAMP ASSY, FOG, LH	1.00	516.00		516.00	
64	4	T89348-33190	CLIP, ULTRASONIC	2.00	12.80		25.60	
65	5	T89348-06110	RETAINER, ULTRASONIC	2.00	16.60		33.20	
66	6	S86560-06110	HORN ASSY, SECURITY	1.00	145.90		145.90	
67	7	S884A0-06070	CONDENSER ASSY, SUPP	1.00	2166.60		2166.60	
68	8	S16400-F0030	RADIATOR ASSY	1.00	2556.20		2556.20	
69	9	S16470-0V100	RESERVE TANK ASSY, R	1.00	205.90		205.90	
70	0	S16360-F0030	FAN ASSY, W/MOTOR	1.00	4628.60		4628.60	
71	1	T17750-25010	INLET ASSY, AIR	1.00	299.80		299.80	
72	2	S17700-F0030	CLEANER ASSY, AIR W/	1.00	1307.00		1307.00	

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Sublet	
	Lubrication/Fluid	Amount Due	
	Others		

Customer Copy



Borneo Motors

Incheape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.		Customer Details				
Allianz Insurance Singapore Pte Ltd 12 Marina View #14-01 Asia Square Tower 2 Singapore 018961		S1000040 / ALLIANZ		Mrs Grace Yap Mui Huang 681B Jurong West Central 1 #14-72 Singapore 642681 Mobile: 92302911				
		Document No. 0						
		Document Date 27/06/2022						
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2019	AXVA70R	JEZGBT E1	17/06/2019	SKC7177G	0	15995	72/OD/SKC7177G	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MR2B63HK504001631		A25A0331527	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
73	3	S08889-80102 COOLANT, SLLC&&& ?			2.00	86.00		172.00
74	4	T53141-33130 GARNISH, RADIATOR ?			1.00	1091.60		1091.60
<i>Store (LKK)</i> <i>00-M M</i> <i>28/6/22, 12:30pm</i> <i>EXERCISE?</i> <i>P/P</i> <i>M Bel g</i> <i>10 dys</i>								
For & on behalf of		LKK Auto Consultants hence notify the Repairer of the following:			Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd		- To resurvey before after spray painting - To do damaged parts Customer's Signature - Parts prices are subject to information - Third party survey is subject to information - No modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			Parts 35,412.60 Labour 9,412.40 Sublet 440.00 Lubrication/Fluid 0.00 Others 0.00		45,265.00 GST 7.00% 3,168.55 Less 0.00 Amount Due 48,433.55	
Acknowledged by Repairer		Please acknowledge receipt of vehicle						
Signature:								
Date:								

Customer Copy

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	27/06/2022 16:13 (SGT)
Reported by	Driver
Date of Accident	26/06/2022 21:25 (SGT)
Exact Location of Accident	Near 20 Westwood Terrace, Singapore 648603
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKC7177G
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	GRACE YAP MUI HUANG
NRIC No	S1751378H
Email Address	charlesyaphubert@gmail.com
Mobile Phone No	(Phone) +65-88212317
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Camry
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	2487

INSURANCE COMPANY

Name of Insurance Company	Allianz Insurance Singapore Pte. Ltd.
Policy Number / Cover Note Number	-

DRIVER

Name of Driver	CHARLES YAP CHANG YUAN
NRIC No	S9006337E
Date Of Birth	19/02/1990
Occupation	Indoor

Date Of Driving Pass	11/10/2013
Driving experience	8 YEARS AND 8 MONTHS
Gender	Male
Mobile Number	(Phone) +65-88212317
Alt. Phone Number	-
Email Address	charlesyaphubert@gmail.com
Address	SINGAPORE
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Child
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

On the 26/06/2022 at 2125Hrs, I (Veh A:SKC7177G) had exited the PIE at Jalan Bahar. Veh B (SKX7507C) was ahead of me. We entered the filter lane and were about to join the main road at Jalan Bahar. Veh B had crossed the give way line, so I checked for oncoming traffic. As the oncoming traffic was clear, I proceeded to join Jalan Bahar. However, veh B had stopped abruptly. Despite reacting immediately, I could not stop in time and bumped into the rear of vehicle B. When I got off my vehicle, I asked the driver of veh B why he stopped, his reply was that he wanted to give way to an oncoming car. But the vehicle approaching in the oncoming traffic was a good distance away and did not necessitate veh B to stop abruptly.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKX7507C
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-

Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	MARK LIM SOON SHIN
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims,
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firms/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law firms/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date &
Time


Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date
& Time

27th June 2022

1042

Witnessed by Reporting Centre
Personnel



- PLEASE VIEW OVERLEAF -