

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Vimimala

Date: 29 Jun 2022

Preliminary Advice

Vehicle No	: SMN3194B	Accident Date	: 21/06/2022
Make	: BMW 216I	Policy No.	: 30001917024
Assignment Date	: 28/06/2022	Excess	: S\$1,000.00
Date of Inspection	: 28/06/2022	Est. Duration of Repair	: 06
Inspection At	: VANTAGE AUTOMOTIVE LIMITED		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	21,530.37
Revised Amount	:S\$	4,858.79
Check Items (Estimated)	:S\$	14,949.55
Total	:S\$	19,808.34

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	115,000.00
COE / PARF Rebate	:S\$	46,564.00
Salvage Value	:S\$	
Margin for Repair	:S\$	68,436.00

Remarks

- (X) The vehicle is economical for repair
- () The vehicle is not economical for repair
- (X) Part-by-Part repair
- () Lump Sum repair

- (X) Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost .