

**CHENG HOE MOTOR PTE LTD**

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)
QUEK CHIAW HONG
Singapore

Claimant Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP CHINA
Policy No:	DMPCSNW00241052100	Date of Loss:	20/05/2022
Vehicle Reg. No.:	YQ3266U	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	RENUKUMAR CHANDRAKUMAR		

Make/Model:	HINO XZU710R, 4.0 D 14FT WIDE	Vehicle Reg. Date:	09/02/2021
Vehicle Colour:	CAB 5T (M)		
Engine No:	WHITE		
Odometer:	N04CWN12814	Chassis No:	JHHUCV3F10K037078
	0 KM		

Paint Type:
Total Loss? **NO**
Est. Duration of Repair (day) **0**

Not Authorised
Money Hu Pain
@1512-00 3 days

Description of Accident/Loss: REFER SKETCH ATT
Present Location: CHENG HOE MOTOR PTE LTD (YISHUN)

COST OF CLAIMS

	Amount
Parts	
Miscellaneous Items	330.00
Labour	950.00
Paintwork Labour	750.00
owing	0.00
	0.00
Gross Total (S\$)	2,030.00
+ GST 7.00% (S\$)	142.10
Nett Amount (S\$)	2,172.10

This claim is handled by: JUNE PHUA LIAN HUA

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 13 Jul 2022)
 Parts: N/A HINO XZU710R 4.0 D 14FT WIDE CAB 5T (M) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Cheng Hoe Motor Pte Ltd/YQ3266U/13/07/2022 12:13
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC RH TAILLAMP	0.00	0.00	140.00 F
2	1		*1 PC RH TAILLAMP PANEL	0.00	0.00	190.00 F
Total Parts (\$\$)						330.00

F=Franchise part.

Cheng Hoe Motor Pte Ltd/YQ3266U/13/07/2022 12:13. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	1 PC REAR RH MUDFLAP	120.00 X
2	1	1 PC REAR SAFETY BAR	450.00 ✓
3	1	1 PC REAR STEP BAR	380.00 ✓
Sub Total (\$\$)			950.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	1) TO PANEL BEATING	New	400.00
2	2) TO PUITY AND RESPRAY PAINTING	New	350.00
Gross Labour Cost (\$\$)			750.00

Cheng Hoe Motor Pte Ltd/YQ3266U/13/07/2022 12:13. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal mortification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: