

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC6/CT/22006/57/UE23

ASSIGNMENT

From: Date:

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I.: (\$)

☐

: Preli. Report

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

OFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

email: erofia@singnet.com.sg

CHINA

Name : Mohamed Halid (96824714)

Accident Date : 19-Jun-22

Vehicle No : FBH8241C (COE131023)

Vehicle Model : Kawasaki
Z1000M

Estimated Repair Costs

4/s \$4000

27/6/22
Temp. bbl. After mpr

Qty	Description List Items		Amount S(\$)
1	Front fender	one	\$ 480.00
1	Fork tubes assy - L/H	See	\$ 1,932.00 X
1	Fork tubes assy - R/H	See	\$ 1,932.00 X
1	Fork under bracket	un	\$ 1,025.00 X
1	Front rim shaft	1	\$ 185.00 X
2	Front brake discs	See	\$ 1,700.00 X
1	Side mirror (1 set)	2/20	\$ 480.00
1	Handle-bar	Bert	\$ 770.00
1	Handle-bar end (1 set)	0/s	\$ 180.00
1	Front footrests - R/H	cu	\$ 235.00
1	Exhaust assy	cu	\$ 2,800.00
1	Rear footrest	cu	\$ 215.00
			\$ 11,934.00
		Less 10%	\$ 1,193.40
			\$ 10,740.60

Special Net Items

2	Fork oils	11	\$ 56.00 X
2	Fork oil seals	11	\$ 96.00 X
1	Steering cone (1 set)	11	\$ 136.00 X
1	Front sliders (1 set)	cu	\$ 320.00
1	Engine sliders (1 set)	cu	\$ 380.00
1	Engine cover protector (1 set)	cu	\$ 680.00
1	Stickers	ner	\$ 280.00
			\$ 1,948.00

4110
102
3699
1040
380
5119
4092

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

email: erofia@singnet.com.sg

Name : Mohamed Halid (96824714)

Accident Date : 19-Jun-22

Vehicle No : FBH8241C (COE131023)

Vehicle Model : Kawasaki
Z1000M

Estimated Repair Costs

S/No.	Labour	
1	To provide towing service (LOD) \$80.00	\$ -
2	To check wiring and reset headlamp focusing	\$ 17 80.00 X
3	To repair body frame	\$ 17 580.00 X
4	To provide labour	\$ 380 620.00
		\$ 1,280.00
Grand Total		\$ 13,968.60

Singapore Dollars: Thirteen Thousand Nine Hundred Sixty-Eight and Cents: Sixty only


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

Date: _____ Signature: _____

Acknowledged by Repairer: _____

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed
- Part prices are subject to final approval of the insurance company
- To display damaged part(s) during resurvey
- To resurvey before/after repair

Date: _____ Signature: _____

LKK Auto Consultants hence notify the Repairer of the following: