

Shiau Chan (LKKAuto)

From: Simon Ho (LKKAuto)
Sent: Thursday, 11 August 2022 8:27 AM
To: Shiau Chan (LKKAuto)
Subject: Re: SPF-TP SKU 3271Z SURVEYED BY RASUL (OUR REF: CS/SPF22006160/Rqy3)

Dear Shiau Chan,

Audit check done for SKU3271Z, found some parts prices need verification & a labour description wrong. Already told Rasul.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Sent: Wednesday, 10 August 2022 5:43 pm
To: Simon Ho (LKKAuto) <SimonHo@lkkauto.com>
Subject: SPF-TP SKU 3271Z SURVEYED BY RASUL (OUR REF: CS/SPF22006160/Rqy3)

Dear Simon,

For your audit.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)