

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	reginte. Tooser took to door too it					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	F	Ref:	CS/AGI22006167/Vvy3	
		TINSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE		Date:	28/06/2022	
_				Code:		
1.						
	Insured Veh.	SFJ 8008C	Veh. Inspected		SNG 988Y	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10016063/JM	Excess (\$)		0.00	
	Assign From	MAYBIE CHUA	Assign Date		28/06/2022	
2.	. Vehicle Particulars & Condition					
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.	General Information					
	Accident Date	28/06/2022	Inspection Date		28/06/2022	
	Survey held at	vey held at TEAMWORK GARAGE PTE LTD				
		53 UBI AVENUE 1 #01-24 SINGAPORE 408934.				
5a.			lemarks			

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.

B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.