

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : CHINA TAIPING INSURANCE (SINGAPORE) PTE
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111 FAX: 62247175
ATTN: Motor Claim Department \ Motor Claim

Claim Type: Third Party
Accident Date: 24/06/2022
TP Veh Reg No: SNB578H

Estimate No: EST2200204
Date: 12 Jul 2022

Veh Reg No: SMN206X
Make/Model: TOYOTA VIOS 1.5E
AUTO

Chasis No: MR2B23F3601179931
Reg. Date: 23/07/2019
Your Ref No: SNB578H

Estimate Repair Cost to Vehicle No :SMN206X

Quantity	Description	List Price S\$	Amount S\$
Supplementary Parts to Repair			
	List Price		
1	1 PC REAR KEYLESS SENSOR	167.90	
		167.90	
	Less 25%	41.98	125.93
	Total		S\$ 125.93
	GST Amount		S\$ 8.82
	Total Amount Payable		S\$ 134.75

For Kang Car Repairers Pte Ltd


AUTHORISED SIGNATURE