

Lion City Rentals PTE LTD
4 JALAN BESUT

Ms Direct Asia Insurance (Singapore) Pte Ltd

Date 16/03/2020

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO: ~~SLE644T~~ SLH 1920D

CHASSIS NO : GK81004806

MAKE / MODEL : Honda Shuttle 1.5 Auto

DATE OF ACCIDENT : 13/03/2020

YOUR INSURED VEHICLE NUMBER : SKG8295X

MILEAGE: 194219 km

<u>PARTS DESCRIPTION</u>		<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>	
1	Rear tailgate / 00	1PC	\$ 1,850.00	\$ 1,850.00	1193 /
2	Rear tailgate windscreen moulding / NK	1 PC	\$ 195.00	\$ 195.00	135 /
3	Rear back door Hybrid emblem / NK	1PC	\$ 45.80	\$ 45.80	/
4	Rear back door SHUTTLE emblem / NK	1PC	\$ 88.40	\$ 88.40	/
5	Rear tailgate lock / RT	1PC	\$ 550.00	\$ 550.00	305 /
6	Rear tailgate door lock catch X NK	1PC	\$ 158.00	\$ 158.00	X
7	Rear tailgate weatherstrip / TN	1PC	\$ 380.00	\$ 380.00	197 /
8	R/R taillamp reflector / CRA (LH)	1PC	\$ 850.00	\$ 850.00	340 /
9	R/R taillamp / OR (LH)	1PC	\$ 720.00	\$ 720.00	520 /
10	Rear bumper / OR	1PC	\$ 1,350.00	\$ 1,350.00	985 /
11	Rear bumper RH tow cover X NK	1PC	\$ 68.00	\$ 68.00	X
12	Rear bumper RH side retainer X NK	1PC	\$ 128.00	\$ 128.00	X
13	Rear bumper LH side retainer / OR	1PC	\$ 128.00	\$ 128.00	/
14	Rear bumper LH reflector / CR	1PC	\$ 80.00	\$ 80.00	/
15	Rear bumper LH reflector garnish / CR	1PC	\$ 168.00	\$ 168.00	/
16	Rear bumper inner RH foam ? X NK	1PC	\$ 98.00	\$ 98.00	X
17	Rear bumper inner LH foam ? X NK	1PC	\$ 98.00	\$ 98.00	X
18	Rear end panel / OR	1PC	\$ 950.00	\$ 950.00	685 /
19	Rear end panel top garnish / OR	1PC	\$ 260.00	\$ 260.00	198 /
20	Smart buzzer sensor ? X NK	1PC	\$ 180.00	\$ 180.00	X

LIST TOTAL S\$: \$ 8,345.20

20.00% DISCOUNT S\$: \$ 1,669.04

\$ 6,676.16

SPECIAL NETT

1	Bumper and end panel clips / NK	1 SET	30 /	\$ 200.00	
2	Reverse sensor / SHD	1 SET	220 /	\$ 260.00	
3	Windscreen sealant / NK	1PC	40 /	\$ 100.00	
4	Body sealant / NK	1PC	40 /	\$ 200.00	

Special Nett Total S\$: \$ 760.00

LABOUR CHARGES

- To labour charge for removing rear back door, rear end panel, spare panel and rear bumper to facilitate repairs and replacement of damaged parts \$ 1,200.00 1000

- 2 To respray rear bumper, rear back door ,
spare tyre panel and end panel \$ 1,200.00 900
- 3 Transfer door mechanism to facilitate repairs
and replacement of parts (Take) \$ 120.00 50
- 4 To remove & install rear windscreen glass \$ 180.00 120

LABOUR TOTAL S\$: \$ 2,700.00
TOTAL S\$: \$ 10,136.16
7% GST \$ 709.53
GRAND TOTAL S\$: \$ 10,845.69

= 6776.96

L/S - 5421.56
= 5400

Store (LKK)

30/6/22, 10.10

m R

L/S

by AC Y
5 L/S

LKK Auto Consultant - Lince notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date: