

TP Great American SKU 9638K 2009 March.
VERON. Hyundai Avante 1591CC
KMH DU41BR9U712031

Rees Buyer	Defend	\$58.30 ✓
Rees Buyer Clips.	✓	30(SN). ✓
Rees Buyer Side Holder x 02	✓	$38.4 \times 2 = 76.80$ ✓
Rees Buyer Sponge	Anti d	129.40 ✓
Rees Buyer Reinforcement	Anti d	298.70. ✓
Rees Buyer Reinforcement Stay x 02	✓	18 x 5 = 90. +
Rees Buyer Reinforcement Bracket x 05		280(SN) 200(SN)
Reverse Sensor	Defend	485.10. +
Rees End Panel.	Rejs	188.50. +
Rees End Panel Top Garnish	HP	20(SN) +
Rees End Panel Top Garnish Clips	✓	60(SN) +
Rees End Panel Sealant.	HP	

106370

85096

S-N: 230

SKU 9638K

Panel Benty

Spry Painting.

Wiring.

To remove reverse sensor

To spray tuff coat 920.

To remove upholstery.

~~800.~~ 400

~~600~~ 400

~~50~~ 30

~~100~~ 50

~~150~~ 400

150. +

Total: 2000.96

4/s: 1.6K

02 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1,600