



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD			Ref:	CS3/SMR22005102/Rvy3m4-1
60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Date:	04/07/2022
			Code:	SMR
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 5025R	Veh. Inspected	SFH 5000D
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/05/22/2073	Excess (\$)	0.00
	Assign From	ANA MAGNAYE	Assign Date	29/06/2022
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ C180 A-V	c.c	1595
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	WDD2050402R199678	Colour	RED
	Odometer	114128 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/50 R17	CONTINENTAL	6 mm
	L/H Front Tyre	225/50 R17	CONTINENTAL	6 mm
	R/H Rear Tyre	225/50 R17	CONTINENTAL	6 mm
	L/H Rear Tyre	225/50 R17	CONTINENTAL	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	25/05/2022	Inspection Date	31/05/2022
	Survey held at	SOON LEE CHOON AUTO SERVICES BLK 5032 ANG MO KIO IND.PARK 2 #01-283 . SINGAPORE 569535		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	