



PREMIUM AUTOMOBILES



55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate-1

Veron.

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0518/2022/JT

28-Jul-22

CHANG

1 of 1

SLS 5030 M

AUDI E-TRON SB ADVANCE

Quantity	Description	Unit Price	Amount
Labours			
1	TO REMOVE AND REINSTALL AIRCON CONDENSER AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$ 1,800.00	✓
2	TO CARRY OUT VACUUM AND REGAS FOR R1234yf.	S/N \$ 1,200.00	✓
3	TO DISMANTLE AND RENEW FRONT LOCK CARRIER, ALIGN TO POSITION.	\$ 2,400.00	1800. ✓
Parts			
1	FRONT BUMPER GUIDE - RH <i>brand</i>	\$ 50.00	✓
2	FRONT LOCK CARRIER <i>cracked</i>	\$ 1,283.00	✓
3	FRONT FENDER BRACKET - RH <i>brand</i>	\$ 76.00	✓
4	SPREADER RIVET <i>me</i>	\$ 76.00	✓
5	RADIATOR AIR GUIDE - UPPER <i>brand</i>	\$ 88.00	✓
6	ADJUSTING ELEMENT	\$ 140.00	✓
7	COOLANT <i>new</i>	\$ 297.00	✓
GRAND TOTAL		\$ 7,410.00	

For Premium Automobiles Pte Ltd

* additional 4 working days.



Authorised Signature

Adrian Ling Resmaged.

To add 4 days. for the replacement of lock carrier. and other resupply and supplementary items.