

ASS. REC. BY:

REF:

A15/22 006276/KC

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

12 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GY 6233R

Yr Regn:

06, 05

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NIS Unvan

c.g

2953

Colour

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

396183

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JN114G 2825 80701170

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F: B.S 195R15X8

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

9

mm

Rear

R/Bal.

2

mm

L/Bal.

9

mm

L/Bal.

2

mm

D.O.A.

27/6/12

D.O.I.

1/7/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

Fines

Others

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech Invs (\$)

☐

: Weekend (\$)

TOTAL

Report Format:

Lump Sum / I.B.I: (\$)

TSR AUTOMOTIVE PTE LTD

UEN No. 202201279H

160 Sin Ming Drive, #06-15

Sin Ming Auto City, Singapore 575722

Email: tsrteamworks2022@gmail.com

Not Authorized
11/1/22
Preserving After Repair

Date : 28/06/2022

QUOTATION -THIRD PARTY CLAIM

ALLIANZ INSURANCE SINGAPORE PTE LTD

Attn: Motor Claim Department . Officer In Charge

Accident on : 27/06/2022

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insured Party

Veh No : GY 6233 R
Model : NISSAN URVAN
Insured Ins: NTUC INCOME

QTY	PARTICULARS	AMOUNT	SURVEYOR
	Your Insurer Vehicle No : YM 8987 K		
1	TAILGATE	\$ 1,895.00	✓
1	TAILGATE W/SASCREEN RUBBER	\$ 380.00	50% ✓
1	TAILGATE W/SCREEN	\$ 1,685.00	✓
1	TAILGATE TRIM BOARD	\$ 480.00	✓
1	TAILGATE TOP MIRROR	\$ 360.00	?
2	TAILGATE HINGES	\$ 360.00	X
2	TAILGATE ABSORBERS	\$ 480.00	?
1	TAILGATE WIPER MOTOR	\$ 685.00	?
1	TAILGATE WIPER ARM	\$ 260.00	?
1	TAILGATE WIPER ARM COVER	\$ 121.00	✓
1	TAILGATE CENTER LOGO	\$ 65.00	✓
1	TAILGATE TRIM BOARD SIDE TOPS	\$ 578.00	?
1	TAILGATE OUTER GARNISH	\$ 420.00	✓
2	TAILGATE No. PLATE LAMP	\$ 280.00	?
1	TAILGATE OUTER HANDLE	\$ 165.00	X
2	TAILLAMPS	\$ 798.00	✓
2	TAILLAMP PANEL INNER	\$ 396.00	X
2	TAILLAMP PANEL OUTER	\$ 446.00	?
2	TAILLAMP SIDE CLIPS	\$ 40.00	✓
2	TAILLAMP LOWER BRACKETS	\$ 280.00	?
1	REAR FENDER PANEL LH	\$ 3,581.00	✓
1	REAR FENDER PANEL RH		
1	END PANEL	REPAIR	
1	END PANEL TOP METAL STRIP	\$ 460.00	✓
1	FLOOR PANEL	\$ 330.00	?
1	SPARE TYRE BRACKET / HOLDER	\$ 2,800.00	X
1	REAR BUMPER	\$ 468.00	?
2	REAR BUMPER SIDE BRACKETS	\$ 780.00	✓
1	REAR BUMPER CENTER STEP PANEL	\$ 180.00	✓
1	REAR BUMPER CENTER STEP GARNISH	\$ 265.00	✓
2	REAR BUMPER CENTER BRACKETS	\$ 350.00	X
1	REAR EXHAUST	\$ 220.00	?
		\$ 850.00	?
		\$ 20,458.00	
	Less 10 %	\$ 2,045.80	
		\$ 18,412.20	

TSR AUTOMOTIVE PTE LTD

UEN No. 202201279H

160 Sin Ming Drive, #06-15

Sin Ming Auto City, Singapore 575722

Email: tsrteamworks2022@gmail.com

S/NETT PARTS			
2	REAR W/SCREEN SEALANT	\$ 140.00	405m
1	70KM/H STICKER	\$ 20.00	155m
1SET	TAILGATE COMPANY STICKERS (Bill)	\$ 1,000.00	?
1SET	REAR LH PANEL COMPANY STICKERS (Bill)	\$ 500.00	?
1SET	REAR RH PANEL COMPANY STICKERS (Bill)	\$ 500.00	?
1	REAR No.PLATE	\$ 50.00	205m
1SET	REVERSE SENSORS	\$ 300.00	2005m
1SET	REVERSE CAMERA	\$ 400.00	?
1	TAILGATE WIPER BLADE	\$ 68.00	x
1	SPARE TYRE	\$ 580.00	?
TOTAL S/NETT		\$ 3,558.00	
TOTAL PARTS :		\$ 21,970.20	
QTY	LABOUR	AMOUNT	SURVEYOR
	Balance b/f	\$ 21,970.20	
	<u>LABOUR CHARGES</u>		
	Labour charges to do cutting welding, on side panel, end panel, floor panel etc , replace repair accident affected area	\$ 1,800.00	1400l
	To replace rear exhaust	\$ 150.00	60l
	To install rear w/screen	\$ 120.00	✓
	Transfer tailgate parts to another tailgate	\$ 140.00	60l
	Remove refix , garnish , side board upholstery etc	\$ 200.00	80l
	To check lamp wiring system for accident affected area	\$ 120.00	20l
	To install replace reverse camera, reverse sensors .	\$ 150.00	60l
	To repair rear chassis body alignment	\$ 300.00	x
	To do anti rust	\$ 120.00	90l
	To do spray painting on accident affected area , inner and outer	\$ 1,400.00	1100l
	To do sealant seal gap, waterproofing on cutting welding accidentn affected area	\$ 200.00	60l
Total Labour :		\$ 4,700.00	
Total Parts & Labour :		\$ 26,670.20	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	28/06/2022 16:43 (SGT)
Reported by	Driver
Date of Accident	27/06/2022 10:20 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	TPE HIGHWAY
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GY6233R
-----------------------------	---------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	CHAMPION REPUBLIC PTE LTD
Company Reg No	2XXXXX175E
Email Address	CHAMPIONKING777@GMAIL.COM
Mobile Phone No	(Phone) +65-98252696
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Nissan
Model	Urvan
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Manual
CC	2953

INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Policy Number / Cover Note Number	5117702061-02

DRIVER

Name of Driver	NGOOI TEE HWA
NRIC No	SXXXXX119B
Date Of Birth	22/08/1978
Occupation	Outdoor



REMARKS
POLICE REPORT



12072007702-12

Police Station of Origin:
Marine Parade N.P.C.
300 Marine Parade Road SINGAPORE
449296
Tel No: 1830-4428999

2 of 3

Report No. 16020152/021-1

CONTINUATION OF REPORT

Driver	
Name	NGOOI TEE HWA
Related Vehicle	QY6233R (Van)
Hospital/Clinic	NIL
Date Treatment	NIL
No. of Days granted Medical Leave	NIL
ID No.	S7873119B
Contact No.	95252698
Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Discharge	NIL
Degree of Injury	Slight

Brief Details.

On 27 June 2022 at about 1025hrs, I was driving on TPE towards Yishun. I believe there was road works ahead as such, the traffic was moving slowly. I am the driver of a Nissan Van bearing vehicle number GY6233R.

Just before the Jalan Kayu Exit, the rear of my van collided with the front of a Mitsubishi Fuso Lorry bearing vehicle number YM8987K. The rear of my van was damaged with the glass panel shattered and the door dented. No passenger was in my van. The lorry driver offered for a private settlement however I did not want to. I did not exchange particulars with the lorry driver. As such, I called for police assistance and traffic police assisted me. Subsequently, I was conveyed to the hospital and was given 2 days MC. I have no visible injuries, however, feel uncomfortable. Eventually, traffic police handed over my van to my colleague which was towed to the workshop.

I am lodging this report for insurance purposes.