

Profi Automotive

10 Kaki Bukit Road 2 #01-05
 First East Centre
 Singapore 417868
 ☎ 94335558
 📠 94335558
 profi.automotive@asia.com

QUOTATION

Q0635

DATE

30/06/2022

TOTAL

SGD S\$23,460.50

TO

China Taiping Insurance (Singapore) Pte Ltd || SNA9943Z - Mercedes Benz GLB

DESCRIPTION	UNIT PRICE	QTY	DISCOUNT	AMOUNT
Front bumper ✓ BR Listed item	1477.53	1	-S\$235.00 16%	S\$2,115.00
Front bumper grille emblem ✓ SK (LOGO) Listed item	725.19	1	-S\$87.00 12%	S\$783.00
Front bumper grille ✓ BR Listed item	1017.37	1	-S\$108.90 11%	S\$980.10
Front bumper grille - lower ✓ / cut Listed item	128	1	-S\$39.80 31%	S\$358.20
Front bumper number plate moulding ✓ SK Listed item	40(SN)	1	-S\$10.00 10%	S\$90.00
Front PDC sensor X Listed item	S\$375.00	6	-S\$225.00 10%	S\$2,025.00
Front PDC sensor holder X SK Listed item	S\$60.00	6	-S\$36.00 10%	S\$324.00
Front radar distant sensor ✓ NW Listed item	1400.00 ✓	1	-S\$179.00 13%	S\$1,611.00
Front radar distant sensor bracket ✓ BT Listed item	60	1	-S\$12.00 10%	S\$108.00
Front bumper retainer LH X SK Listed item	S\$155.00	1	-S\$15.50 10%	S\$139.50
Front bumper retainer RH X SK Listed item	S\$155.00	1	-S\$15.50 10%	S\$139.50
Front headlamp LH X NN Listed item	S\$5,590.00	1	-S\$559.00 10%	S\$5,031.00
Front headlamp RH X NN Listed item	S\$5,590.00	1	-S\$559.00 10%	S\$5,031.00
Front grille emblem ✓ MC (AMG) Listed item	110	1	-S\$31.10 10%	S\$279.90
Front number plate ✓ SK S/Nett item	40(SN)	1		S\$100.00
Front bumper clip - 1 set ✓ MC S/Nett item	S\$50.00	1		S\$50.00
Front bumper grille clip - 1 set ✓ MC S/Nett item	30	1		S\$50.00
Front camera X NN S/Nett item	S\$1,200.00	1		S\$1,200.00
Check wiring and lightning system Labour front	S\$100.00	1		S\$100.00

5298.09

-10%: 4768.28

DESCRIPTION	UNIT PRICE	QTY	DISCOUNT	AMOUNT
Remove and renew front sensor Labour	S\$150.00	1	40	S\$150.00
Remove and renew front radar sensor Labour	S\$150.00	1	40	S\$150.00
Diagnose check, clear fault code Labour	S\$600.00	1	150	S\$600.00
Front radar sensor calibration and adaption Labour	S\$800.00	1	200 7	S\$800.00
Panel beating on affected areas Labour	S\$1,000.00	1	300	S\$1,000.00
Spray painting on affected areas Labour	S\$800.00	1	300	S\$800.00
Apply anti-rust on affected areas Labour	S\$150.00	1	NNX	S\$150.00
TOTAL			1060	SGD S\$23,460.50

Thank you for your business!

5988.28

4 Days.

L/S Repair

After repair photos.

Emo Q:amp.

8288 0282

1/7/2022.

Excess: \$1000

Not Authorized

LS \$4750.00

LNK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications are allowed
- Supplemental parts must be resurveyed and is subject to approval from insurance Company

Acknowledged by: _____
Signature: _____
Date: _____