

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE I	PTE LTD		Ref:	CC4/ASM22006292/Upa3q2	
	8 SHENTON WAY AXA TOWERSING			Date:	20/09/2022	
	ATTN:CYNTHIA			Code:	ASM	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SHD 5131G	Veh. Inspected	l	SLZ 155H	
	Policy No.	P2459880	Coverage (\$)		0.00	
	Claim No.	S2M045MO	Excess (\$)		0.00	
	Assign From		Assign Date		01/07/2022	
2. Vehicle Particulars & Condition						
	Make & Model	KIA SORENTO (A)	c.c		2199	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	KNAPH81BMJ5448537	Colour		BLACK	
	Odometer	22419 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	235/60 R18	YOKOHAMA		8 mm	
	L/H Front Tyre	235/60 R18	YOKOHAMA		8 mm	
	R/H Rear Tyre	235/60 R18	YOKOHAMA		8 mm	
	L/H Rear Tyre	235/60 R18	YOKOHAMA		8 mm	
4.	1. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	29/06/2022	Inspection Dat	е	01/07/2022	
	Survey held at	rvey held at ASIA MOTORSPORTS SOLUTION PTE LTD				
		37A EVERITT ROAD SINGAPORE 428586				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days					
	•					