



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: LOH CYNTHIA		Ref: CS3/ASM22006302/Tcy3e2 Date: 02/12/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)			
Insured Veh.	SHD 4531S	Veh. Inspected	SJJ 7663U
Policy No.	VFX/P2419138	Coverage (\$)	0.00
Claim No.	S2M045NF	Excess (\$)	0.00
Assign From	LOH CYNTHIA	Assign Date	01/07/2022
2. Vehicle Particulars & Condition			
Make & Model	HONDA STREAM	c.c	1799
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	RN61070284	Colour	WHITE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/65 R15	TOURADOR	6 mm
L/H Front Tyre	205/65 R15	TOURADOR	6 mm
R/H Rear Tyre	205/65 R15	TOURADOR	6 mm
L/H Rear Tyre	205/65 R15	TOURADOR	6 mm
4. Description of Damages			
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
5. General Information			
Accident Date	29/06/2022	Inspection Date	27/09/2022
Survey held at	27A #01-15/27 JURONG PORT ROAD SINGAPORE 619101		
Repairer	AUTOFRIEND SERVICES		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		15 Working Days	