

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0546/2022/JT
DATE : 30-Jun-22
WIP : 30928

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 1/7/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Steve

~~13~~ days exclude 1 PH & 2 Sun

With suspension repairs.

Johnny Boo 28 Oct 22

11 days

OWNER'S NAME : MRS CHONG SI MIN, BERICA
ADDRESS : 10 TAO CHING ROAD
#18-19
SINGAPORE 618725
TELEPHONE : HP +65 93827057
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070132145
VEHICLE NO : **SMV 492 T**
MODEL CODE : AUDI Q3 1.4 TFSI S TRONIC
MODEL YEAR : 14/9/2020
ENGINE NO : CZD 897824
CHASSIS NO : WAUZZZF37L1116763
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 29-Jun-22
PLACE OF ACCIDENT : FOUNTAIN ROUNDABOUT

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 492 T - FRONT

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00		
3	TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	800.00	\$	560.00
4	TO REMOVE AND RENEW RHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME.	S/N \$	2,400.00	\$	2,400.00
5	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, RHS FRONT DOOR AND RHS REAR DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	4,000.00	\$	1,000.00
6	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, RHS FRONT DOOR, RHS WING MIRROR COVER, RHS REAR DOOR AND DOOR HANDLE.	\$	4,500.00	\$	2,460.00
SUB TOTAL LABOUR CHARGES		:	\$ 12,580.00	\$	6,900.00



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 492 T - REAR

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		c/f	\$	6,900.00
1	TO REMOVE AND TRANSFER REAR PARKING AND AND REAR LID KICK SENSOR.	S/N	\$ 360.00	\$ 360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.		\$ 1,600.00	\$ 500.00
3	TO RESPRAY REAR BUMPER AND RHS REAR FENDER.		\$ 2,000.00	\$ 550.00
4	TO RENEW RHS FRONT TYRE WITH RIM AND RHS REAR RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT. <i>(Suspension repairs)</i>	S/N	\$ 560.00	\$ 560.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 17,292.00	\$ 9,062.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 492 T - FRONT

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 1,073.00	\$	858.40
2	FRONT BUMPER CLOSING ELEMENT - RH	1	\$ 66.00		
3	FRONT BUMPER GRILLE - RH	1	\$ 124.00		
4	FRONT BUMPER CLOSING ELEMENT	1	\$ 212.00		
5	FRONT BUMPER SPOILER	1	\$ 426.00		
6	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 171.00		
7	HEADLIGHT MOUNTING - RH	1	\$ 132.00		
8	HEADLIGHT - RH	1	\$ 5,952.00		
9	LIFT CYLINDER - RH	1	\$ 231.00		
10	LIFT CYLINDER HOSE	1	\$ 92.00		
11	FRONT BUMPER GUIDE SECTION - RH	1	\$ 43.00		
12	FRONT FENDER - RH	1	\$ 1,445.00		
13	FRONT FENDER ATTACHMENT PARTS	1	\$ 66.00		
14	FRONT FENDER BRACE - RH	1	\$ 98.00		
15	FRONT FENDER BRACKET - RH	1	\$ 39.00		
16	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 37.00		
17	FRONT FENDER INSULATION - RH	1	\$ 48.00		
18	FRONT WHEEL HOUSING LINER - RH	1	\$ 260.00		
19	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 105.00		
20	FRONT WHEEL HOUSING LINER COVER - RH	1	\$ 18.00		
SUB TOTAL SPARE PARTS		:	\$ 10,638.00	\$	858.40

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 492 T - FRONT

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	<i>858.40</i>
21	FRONT WHEEL ARCH COVER - LH / RH	2	\$ 566.00	\$	<i>452.00</i>
22	FRONT DOOR - RH	1	\$ 3,017.00		
23	FRONT DOOR OUTER SEAL - RH	1	\$ 185.00		
24	FRONT DOOR ATTACHMENT PARTS	1	\$ 164.00		
25	FRONT DOOR CATCH - RH	1	\$ 134.00		
26	FRONT DOOR COVER - RH	1	\$ 283.00	\$	<i>226.00</i>
27	WING MIRROR MOUNTING - RH	1	\$ 2,278.00	\$	<i>1,822.40</i>
28	WING MIRROR CAP - RH	1	\$ 203.00	\$	<i>162.40</i>
29	WING MIRROR GLASS - RH	1	\$ 1,052.00		
30	FRONT DOOR CORNER TRIM - RH	1	\$ 51.00	\$	<i>40.40</i>
31	FRONT DOOR WINDOW GUIDE - RH	1	\$ 481.00		
32	FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - RH	1	\$ 287.00	\$	<i>229.60</i>
33	FRONT DOOR WINDOW SLOT SEAL TRIM STRIP - RH OUTE	1	\$ 251.00	\$	<i>200.80</i>
34	REAR DOOR - RH	1	\$ 3,127.00		
35	REAR DOOR OUTER SEAL - RH	1	\$ 151.00		
36	REAR DOOR ATTACHMENT PARTS	1	\$ 324.00		
37	REAR DOOR CATCH - RH	1	\$ 134.00		
38	REAR SILL PANEL SEAL - RH	1	\$ 151.00		
39	REAR DOOR COVER - RH	1	\$ 270.00	\$	<i>216.00</i>
40	REAR WHEEL HOUSING LINER - RH	1	\$ 262.00		
SUB TOTAL SPARE PARTS		:	\$ 13,371.00	\$	<i>4,208.00</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 492 T - FRONT

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		\$ 4,208.00
41	REAR WHEEL SPOILER - RH	1	\$ 44.00	
42	SIDE MEMBER TRIM - RH	1	\$ 189.00	
43	REAR DOOR HANDLE, EXTERIOR - RH	1	\$ 222.00	
44	REAR DOOR HANDLE HOUSING - RH	1	\$ 31.00	
SUB TOTAL SPARE PARTS		:	\$ 486.00	\$ 4,208.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 492 T - REAR

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		c/f		\$	4,208.00
1	REAR BUMPER	1	\$ 1,738.00		
2	REAR BUMPER FIXING PARTS	1	\$ 220.00		
3	REAR BUMPER SPOILER	1	\$ 510.00	\$	408.00
4	REAR BUMPER CROSS REINFORCEMENT - CENTER	1	\$ 108.00		
5	REAR BUMPER BRACKET - RH	1	\$ 53.00		
6	REAR LIGHT REFLECTOR - RH	1	\$ 46.00		
7	REAR BUMPER GUIDE SECTION - RH	1	\$ 71.00		
8	REAR WHEEL ARCH COVER - LH / RH	2	\$ 566.00	\$	452.00
9	REAR ALUMINIUM RIM	2	\$ 2,828.00	\$	1,131.20
10	RUBBER VALVE	4	\$ 15.00	\$	2.96
11	SUSPENSION SUBFRAME ASSEMBLY CARRIER	1	\$ 751.00		
12	SUBFRAME BONDED BRUSHES - UPPER / LOWER	1	\$ 178.00		
13	SUSPENSION TRACK CONTROL ARM	1	\$ 511.00		
14	SUSPENSION WHEEL BEARING HOUSING - RH	1	\$ 751.00	\$	600.80
15	SUSPENSION WHEELHUB BEARING	1	\$ 549.00	\$	438.80
16	SUSPENSION GUIDE JOINT - RH	1	\$ 145.00	\$	115.60
17	SUSPENSION DRIVE SHAFT - RH	1	\$ 1,517.00		
18	COUPLING ROD	1	TBC		
19	STABILIZER	1	\$ 456.00		
20	GAS SHOCK ABSORBER	1	\$ 338.00	\$	270.40
SUB TOTAL SPARE PARTS		:	\$ 11,351.00	\$	7,627.76

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 492 T - REAR

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	7,627.76
21	STEERING GEAR	1	\$ 5,538.00		
22	TRACK ROD	1	\$ 98.00		
23	TIE ROD END - RH	1	\$ 126.00	\$	100.40
24	RHS FRONT TYRE	S/N	\$ 310.00	\$	310.00
26	SUNDRIES		\$ 900.00	\$	81.68
TOTAL SPARE PARTS		:	\$ 42,818.00	\$	8,119.84
TOTAL LABOUR CHARGES		:	\$ 17,292.00	\$	9,062.00
GRAND TOTAL		:	\$ 60,110.00	\$	17,181.84

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.
BL-02/08/22