

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM22006317/Tcy3m4 8 SHENTON WAY #24-01 AXA TOWER Date: 22/07/2022 SINGAPORE 068811 ATTN: ANG YVONNE Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SBQ 7777H** CB 7364H Veh. Inspected Policy No. GA062357 Coverage (\$) 0.00 Claim No. S2M045E2 Excess (\$) 0.00 ANG YVONNE **Assign Date** 04/07/2022 Assign From **Vehicle Particulars & Condition** 2. NISSAN NV350 Make & Model 2488 c.c HIDDEN 2014 Engine No. Year of Reg. JN1TC2E26Z0000807 SILVER Chassis No. Colour Odometer 298173 KM Steering **IN ORDER IN ORDER** NIL **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 195/R15 FRONWAY 6 mm **FRONWAY** L/H Front Tyre 195/R15 6 mm 195/R15 **FRONWAY** R/H Rear Tyre 6 mm **FRONWAY** L/H Rear Tyre 195/R15 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION AND REAR PORTION. 5. **General Information** 27/06/2022 04/07/2022 (12:08 PM) Inspect Date / Time Accident Date 48 TOH GUAN ROAD EAST #02-126 ENTERPRISE HUB SIN Survey held at SINCERELEAD GARAGE PTE LTD Repairer 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$8,000

Report Ref No. CS3/ASM22006317/Tcy3m4

Estimate Days of Repair

Inspected By

5b.

MOHAMAD TAUFIKH

ESTIMATED NORMAL PERIOD FOR REPAIR:

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A
Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

10 Working Days

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.