

DETAILS

nice

Source: MRM-SG

Version: 1.0 (Last Synchronised: 02 Jul 2022)

143

VOLKSWAGEN JETTA 1.4 TSI 1622G5 (A) (Catalogue:Merimen Singapore 1.0)

Repairer's

(Price-denominated Standard List)

Print Code: Kan Fook Sing Motor Workshop/SKF6234R/02/07/2022 10:01

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

Estimates on Parts				%Disc	%Depr	Amount	
No.	Qty	Part No.	Particulars				
1	1		*FRONT FENDER LH	DT	0.00	0.00	*230.00 F
2	1		*FRONT FENDER VERTICAL GARNISH LH	acc DT	0.00	0.00	*85.00 F
3	10		*FRONT FENDER SHIELD CLIP	DT	0.00	0.00	*55.00 F
4	1		*FRONT DOOR LH	DT	0.00	0.00	*850.00 F
5	1		*FRONT DOOR HINGE TOP LH	Shf	0.00	0.00	*45.00 F
6	1		*FRONT DOOR HINGE LOWER LH	Shf	0.00	0.00	*65.00 F
7	1		*FRONT DOOR CHECKER LH	SVC X Shf	0.00	0.00	*55.00 F
8	1		*FRONT DOOR TOP MOULDING LH	SVC X	0.00	0.00	*110.00 F
9	1		*FRONT DOOR OUTER MOULDING LH	Nec	0.00	0.00	*65.00 F
10	1		*FRONT DOOR OUTER HANDLE LH	Cia	0.00	0.00	*100.00 F
11	1		*FRONT DOOR SIDE MIRROR LH	Cia	0.00	0.00	*140.00 F
12	1		*FRONT DOOR SIDE MIRROR COVER LH	Cia	0.00	0.00	*65.00 F
13	1		*REAR DOOR LH	X	0.00	0.00	*980.00 F
14	1		*REAR DOOR OUTER MOULDING LH	Nec	0.00	0.00	*100.00 F
15	1		*REAR DOOR RUBBER LH	SVC X	0.00	0.00	*85.00 F
16	1		*CENTRE PILLAR GARNISH LH	SVC X	0.00	0.00	*125.00 F
						3 155.00	

F=Franchise part.

Sub Total (S\$)

3,155.00

+ Margin on L,N Items 10.00% (S\$)

315.50

Total Parts (S\$)

3,470.50

Kan Fook Sing Motor Workshop/SKF6234R/02/07/2022 10:01. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

1980

on Miscellaneous Items
 miscellaneous Items selected.

Notes on Labour

Particulars	Lab.Type	Amount
Network Labour	1000 New	1,200.00
SPRAYPAINTING CHARGES		
Labour Items		
2 TO CHECK WIRING SYSTEM	20 NP New	50.00
3 TO TRANSFER DOOR MECHANICISM TO NEW DOOR	30 NP New	100.00
4 TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL WELD CUT PANEL	800 New	820.00
BEAT AND FITTING NEW PARTS		
	Gross Labour Cost (S\$)	2,170.00

Kan Fook Sing Motor Workshop/SKF6234R/02/07/2022 10:01. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Thruvan@Lkhauto.com
 82235769
 5/7/22 1700
 PIP 6days
 not authorise

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

F: 3830
 NP: 6