

Our Job Ref No : 305521481
Date : 30.06.2022

COMFORTDELGRO
ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

FINALIZATION FORM

To : LKK

Fax :

Attn : GUO QIANG

Vehicle Reg No. : SHB4333H

14.07.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- Z The repair job shall bill to: TOKIO S35391MID
2. The finalized amount shall be:
- | | |
|---|-------------------|
| (a) Spare Parts after List discount | <u>\$233.27</u> |
| (b) Labour Charges | <u>\$1,406.00</u> |
| Total for Part-By-Part Repair Cost | <u>\$1,639.27</u> |
| (c) Lumpsum Repair (if applicable) | |
| Total for Lumpsum repair cost after Less: | |
| Final Lumpsum Repair cost | |

3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature : 

Signature : _____

Name : CHIANG

Name : _____

Tel : 62148314

Date : _____

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305521481
REGN NO : SHB4333H
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4A)
DATE OF REGN : 13.12.2019
DATE/TIME IN : 28.06.2022 15:15
ACCIDENT DATE : 28.06.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 03-01-0302-2137-G	CAP WHEEL	1	177.70	25.00	133.27
0002 28-01-0302-2017-A	FUEL TANK LID (PETROL ONL	1	20.00	2.50-	20.00
0003 28-01-9999-2023-A	XX APP LOGO REAR DOOR L/R	1	80.00	0.25	80.00

SUB-TOTAL : 233.27

JOB NATURE

0000 L	MERIMEN FEE	11.00
0001 PB	PANEL BEATING SHB4333H TP	525.00
0002 SP	SPRAYPAINT CHARGE	750.00
0003 20-204	REMOVE/REFIX UPHOLSTERY ASST REPAIR	60.00
0004 20-02	REMOVE/REFIX DOOR PARTS TO ASSIST REP	60.00

SUB-TOTAL : 1,406.00

Total: \$1639.27