

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 04.07.2022

TO : AXA MOTOR CLAIMS DEPTS
VEHICLE NO : SLP7204G
MODEL : TOYOTA ESTIMA AERAS
DATE OF ACCIDENT : 01.07.2022
TIME OF ACCIDENT : 19:50HRS

ACR 500072876

Xiao Tong

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>torn</i>	1	\$ 1,350.00	\$ 1,350.00
2	REAR BUMPER TOW HOOK COVER RH <i>new</i>	1	\$ 30.00	\$ 30.00
3	REAR BUMPER SIDE RETAINER (FRONT) <i>new</i>	2	\$ 78.10	\$ 156.20
4	REAR BUMPER SIDE RETAINER (REAR) <i>new</i>	2	\$ 80.00	\$ 160.00
5	REAR BUMPER SIDE SPONGE RH <i>new</i>	1	\$ 110.00	\$ 110.00
6	REAR BUMPER COVER EXHAUST GARNISH <i>new</i>	1	\$ 95.00	\$ 95.00
7	REAR BUMPER REFLECTOR RH <i>new</i>	1	\$ 89.00	\$ 89.00
8	TAIL LAMP RH <i>new</i>	1	\$ 350.00	\$ 350.00
9	REAR FENDER RH <i>Repair</i>	1	\$ 980.00	\$ 980.00
10	REAR FENDER INNER TRIM RH <i>new</i>	1	\$ 1,370.00	\$ 1,370.00
11	REAR FENDER AIR CON BLOWER C/W MOTOR <i>new</i>	1	\$ 2,980.00	\$ 2,980.00
12	REAR FENDER 1/4 GLASS MOULDING <i>new</i>	1	\$ 910.00	\$ 910.00
13	REAR FENDER LOWER PANEL RH <i>Repair</i>	1	\$ 340.00	\$ 340.00
14	REAR FENDER COWLING RH <i>torn</i>	1	\$ 95.00	\$ 95.00
15	REAR SHOCK ABSORBER RH <i>new</i>	1	\$ 395.00	\$ 395.00
16	REAR WHEEL HUP WITH BEARING RH <i>new</i>	1	\$ 995.00	\$ 995.00
17	REAR AXLE <i>new</i>	1	\$ 3,150.00	\$ 3,150.00

TOTAL PRICE \$ 13,555.20
LESS 25% \$ 3,388.80
SUB TOTAL PRICE \$ 10,166.40

4124.10

3093.07

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER REFLECTOR (SPECIAL TYPE) (SET) <i>new</i>	1	\$ 250.00	\$ 250.00
3	TAIL LAMP CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
4	REAR FENDER RH SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00
5	REAR FENDER INNER TRIM CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
6	REAR FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
7	REAR FENDER GLASS RH SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00
8	REAR FENDER GLASS SEALANT RH INNER SEAL <i>new</i>	1	\$ 40.00	\$ 40.00
9	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
10	REAR EXHAUST COVER GARNISH CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
11	REVERSE SENSOR (4PCS) <i>new</i>	1	\$ 360.00	\$ 360.00
12	REAR WHEEL TYRE RH <i>cut</i>	1	\$ 650.00	\$ 650.00
13	REAR WHEEL RIM RH <i>cut</i>	1	\$ 1,500.00	\$ 1,500.00
14	WHEEL CAP (SET) <i>new</i>	1	\$ 120.00	\$ 120.00
15	BRAKE OIL <i>new</i>	1	\$ 50.00	\$ 50.00

890

TOTAL \$ 3,350.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,600.00	400
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,200.00	400
3	TUFF COAT	\$ 250.00	40
4	REMOVE AND REFIX CUSHION SEAT UPHOLSTRY AND ROOF LINING TO FACILITATE REPAIR	\$ 180.00	50
5	REMOVE AND REFIX REAR AIRCON BLOWER MOTOR	\$ 350.00	180
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	REMOVE AND REFIX REAR QUATER GLASS RH	\$ 100.00	X
8	CONDUCT WATER LEAKAGE TEST	\$ 100.00	X
9	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 350.00	60
10	FOUR WHEEL ALIGHMENT	\$ 120.00	80
11	RESET ABS LIGHT	\$ 350.00	X

12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X
----	---	-----------	---

1260

TOTAL

\$4,860.00

TOTAL PARTS COST : \$ 13,516.40
TOTAL LABOUR COST : \$ 4,860.00
TOTAL REPAIR COST : \$ 18,376.40

Adrian L
2/s 04/07/22
05 Days

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE
CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED
ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR

IRENE

HP : 8297 9787

total: \$243.07

4/s: 4.2k.

4.2k

- LKK Auto Consultants hence notify
the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: