ASS. REC. BY:	TI 22006367 DV43
5 175 m2 =	ASSIGNMENT
From: Date:	Veh No: PC 58697
Estimated Cost:	
OD/TP/WS/TP RES/OD RES/EVA/INV/MV	Type: M.Car / M.Cycle / Bus / Van / Lony / Taxi / Prime Mover /
To Inspect Vehicle No:	Truck/Trailer or Mini Brus
at Workshop m/s	Maker wyota Hiace as 2987
of	Colour SIVN A/G: Insured Std / NI I NA
Insured: YQ 3938P	Sp.Reading 30 2 / 3 T/Radio: Insured / Std / NI / NA
Policy No. DMCVSNW00067372100	Eng/No: 2 KD2673967
21.	C/No: (D+1223002011112
SINIVIZZDZ040 IZ/C0Z/ TAINCI I	Ser Cond Good Fair (Poor / Burnt
(Client's Record)	Steeting: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Brake: Inorder / Jammed / Leaked / Burnt or
	Modi: Nil (S/Rim / STD A/Rim or
(Policy Condition)	Tyre-Size: F: 195715
Remark The veh had seemed to	R: -II
repair at the time of inspection.	O/S BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/
Bal. or Market Value:	TOYO / YOKO or Condor
IDAC Accident Roort Consistent? : Yes of No	R/Bat. C
GIA / PR Seen: Consistent? : Yes or No	178-el mm R/Balt mm
Est Repairs: 5 days Res.: Yes or No	DOA OLO 2222
Lum Sum: % 3 Val.: Yes or No	Survey held at JWG AMK
CA / REV / REP. / 24 HRS	Des. of Damages : Fit / Rear / D/S / N/S / U/C / Rooftop or
Date:Person Contacted: Vehicle: IN / C	Prant Rooftop or
Date/Time Action / Instruction	The UIC / Chassis frame / Body Structure affected due to collision.
Chine Teiping PQ 3938	
1 1 - 1	
(10/22 Junepor 45 5,6001- with	5 days 1 (red 32,168.15, 85%)
tie/Time, File Pass 107 : Prell. Report	Page Of Page In
Final Report	Days Of Repair: 5
ita/fime, File-Return to?	Resurvey No. of Trip: 2 Survey Fee:
13/10/22-typist Add Fe	e: Site linsp (\$)
•	Infonday 15
port Format: Merimen	A FILMES
Production of the contract of	Tech invs (\$) Others
mp Sum / 1.B.J. (\$ 5600	: Weekend (\$

fants terst

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID: Vehicle Details	493B
Vehicle No.:	PC5869Y
Vehicle to be Exported:	Yes
Intended Deregistration Date:	04 Jul 2022
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE COMMUTER GL 3.0 AT 2WD 4DR LWB
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	1KD2673967
Chassis No.:	KDH2230030443
Maximum Power Output:	•
Open Market Value:	\$45,029.00
Original Registration Date:	27 Jun 2017
First Registration Date:	27 Jun 2017
Transfer Count:	1
Actual ARF Paid: Intended PARF Rebate Details	\$2,252.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	
PARF Rebate Amount: Intended COE Rebate Details	\$0.00
COE Expiry Date:	26 Jun 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$38,501.00
COE Rebate Amount:	\$19,164.00
Total Rebate Amount:	\$19,164.00

The information contained herein is correct as at 04 Jul 2022

sgcarmart

Login Sign up

New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products Insurance Articles

Forum

Resources

results/page

PREMIUM AD

PREMIUM AD

Post an Ad

SAVE UP TO \$6



sgcarmart

Post an Advertisement Sell it vourself! Advertise it at just

\$68 until it's SOLD!

Advertiser Login

Ways of Selling

08/2018 Honda Jazz \$69800, \$754 Monthly At 1.88%

GV Automobile Centre 55845



Sort by Date Posted 20 4 vehicles toyota hiace commuter Advanced Search Any Category Reg Date Eng Cap Mileage Veh Type Status Make Model Price Depreciation Available Search Selection toyota hiace commuter Any Any Available Toyota Hiace Commuter 3.0A \$70,800 \$15,160 /yr 06-Mar-2017 2,982 cc Bus Fuel Type: Diesel New paintwork, all the wear and tear done, clean interior, well maintained by previous owner, all seat cushion are as clean as new, flexib... PREMIUM AD

ABS Bus Pte Ltd

Posted: 27-Jun-2022



25-May-2017 2,982 cc Available Toyota Hiace Commuter 3.0A \$70,888 \$14,500 /vr Bus

Fuel Type: Diesel

Look Like New Auto Transmission 13 Seater Toyota Hiace Commuter! Cheapest And Best Unit In The Market! 1 Careful Owner Only! Low...

Net Link Partners Pte Ltd

Posted: 30-Jun-2022



Toyota Hiace Commuter 3.0A \$69,800 \$13,860 /yr 17-Jul-2017 2,982 cc Bus Available GL

Fuel Type: Diesel

Please Call To Arrange For Viewing, Thank You.

Posted: 15-Jun-2022



2,982 cc Available Toyota Hiace Commuter 3.0A \$78,800 \$14,420 /vr 21-Dec-2017 Bus GL High Roof

Fuel Type: Diesel

Over \$12,000 Spent On Interior, Unique Red On Black Upholstery Stand Out from all the Hiace Buses. Modelista Front Grille, Sports Rims...

Posted: 01-Jul-2022

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

Buy / Rent Cars	Sell Your Car	Aftermarket	Articles	General
New Cars For Sale	Post an Ad	Workshop Directory	Car Reviews	About Us
Used Cars For Sale	Sell by Bidding	Aftermarket Products	Car Advice	Contact Us
Cars For Rent	Sell by Consignment		Car News	Careers
			Car Features	Site Map

Res

Follow Sgcarmart.com



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Please report <u>correctly</u> the details of the accident to speed up the claims process.
 This Form must be <u>completed</u> by the Policyholder and/or the Authorised Driver.

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 04/07/2022 13:05 (SGT) Reported by Date of Accident 01/07/2022 11:15 (SGT) **Exact Location of Accident** 528C Pasir Ris Street 51, Singapore 513528 Additional Location Information Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number PC5869Y

INSURED/POLICYHOLDER

Is company? Yes Name Of Registered Owner JEAN-JERRYL TOURS & TRANSPORT SVCS Company Reg No 53259493B jamesanthonysilva@hotmail.com **Email Address** Mobile Phone No (Phone) +65-84208702 Alternative Phone No.

VEHICLE PARTICULARS

Manufacturer Toyota Model Hiace Variant

Exact purpose for which vehicle was being used at time of Employment accident

Are you claiming under your own insurance policy for repair to No - Claiming third party your vehicle? Vehicle Category Commercial vehicle

Transmission Auto CC 2982

INSURANCE COMPANY

Name of Insurance Company Great American Insurance Company Policy Number / Cover Note Number MOMVC000008552-02-000

DRIVER

Name of Driver HO JENSON, JOHN @ YOCHANAN ELIYAHU BEN HASSAN NRIC No S7630617F Date Of Birth 29/09/1976 Occupation Outdoor

Accident report SN0922740005

Date Of Driving Pass 20/01/2014 Driving experience 8 YEARS AND 6 MONTHS Gender Mobile Number (Phone) +65-96581040 Alt. Phone Number Email Address yochanan_netsarim@yahoo.com Address BLLK 538 ANG MO KIO AVENUE 5 #03-4036 Address complement Postcode 560538 Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Employee Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? Yes Was any injured conveyed to hospital by ambulance? No Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) 1 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement DETAILS OF POLICE ACTION Was the accident reported to the police? Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT PLEASE REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YQ3938P
Vehicle Manufacturer	4
Vehicle Model	
Vehicle Variant	
Vehicle Colour	
Vehicle Category	Commercial vehicle
Name of Driver	
Contact Number	

Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	_
No. Of Passenger (Including Driver)	_

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	HO JENSON, JOHN @ YOCHANAN ELIYAHU BEN HASSAN
Gender	Male
Phone No	(Phone) +65-96581040
Address	
Address Complement	
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	SLIGHT INJURY
Injured person in which vehicle?	PC5869Y
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

- Pease report correctly the details of the accident to speed up the claims process.
- This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association
- of Singapore (GA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that

- (a) My insurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administaring my claims (including the maling of correspondence, statements, invoices, reports or notices to ma, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

JEAN-JERRYL TOURS & TRANSPORT SVCS


REG. NO: 53259493B BLK 447A JALAN KAYU #06-366 SINGAPORE 791447 HP: 8420 8702 FAX: 6444 9655

Employed Spharus (Pale a Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre

Personnel

Sketch Plan



Van A - PC58694 Veh 5 - YQ 5938 P

Describe Circumstances of the Accident
On the above mention date and have, I was wanted to exit gently
at Paule Ris STS1 Bik 5230. Smildenly rehicle YQ39338P infront of my reverse about the
onto my vehicu. My vehicu's front portion was dominged. We exchange particulari
ound left the scene.

Declaration


We declare the foregoing particulars are true in every respect.

JEAN-JERRYL TOURS & TRANSPORT SVCS

REG. NO. 532594938
BLK 447A JALAN KAYU #06-368
SINGAPORE 791447
HP: 8420 8702 FAX. 6444 9655
PERPHICHER'S EIGHBRAN PIXAL DITORNS Signature (# driver is not the policyhoider) / Date

Personnel



















JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 9698 8882 | FAX: 6909 9592 E-Mail: jwg.claims@yahoo.com

To: CHINA TAIPING
Att: Motor Claims Dept

ACCIDENT INVOLVING SME646G [YOUR INSURED] & PC5869Y [OUR CLIENT] ON 01/07/2022.

ESTIMATED REPAIR COSTS FOR PC5869Y

QTY	PARTS	A	MOUNT
			48
2PCS	HEAD LAMP LH / RH @ \$3,689.10 EACH money wate 2420.50 x 2	\$	7,378.20
2PCS	HEAD LAMP WIREHARNESS LH / RH @ \$1,891.29 EACH ►	\$	3,782.58
1PC	BONNET Death 1020-30	\$	1,180.51
1PC	BONNET TOYOTA LOGO HLO	\$	79.10
l PC	BONNET SEAL SW	\$	81.92
lPC	BONNET LOCK 128.00	\$	583.00 L
PCS	BONNET HINGE LH / RH	\$	382.00
PC	BONNET STAND HIM	\$	147.00
PC	FRONT GRILLE ASSY many broken 581-10	\$	1,082.60
PC	FRONT BOTTOM HS	\$	829.00
PC	FRONT GRILLE TOP CHROME	\$	329.00
PC	FRONT GRILLE CENTER CHROME	\$	316.00
PC	FRONT GRILLE BOTTOM CHROME HM	\$	337.50
PC	FRONT BUMPER HIM	\$	849.80
PC	FRONT BUMPER LOWER GRILLE	\$	385.91
PCS	FRONT BUMPER SIDE RETAINER LH / RH @ \$103.40 EACH	\$	206.80
PCS	FRONT BUMPER FOG LAMP LH / RH @ \$410.59 EACH	\$	821.18
PC	FRONT BUMPER TOW HOOK COVER	\$	69.80
PCS	FRONT BUMPER PARKING SENSOR	\$	649.00 ×
PC	FRONT INTER-COOLER ASSY pundul 1108-60	\$	3,492.84
PC	FRONT INTER-COOLER ASSY OUTER GARNISH (1)	\$	392.00
PC	FRONT RADIATOR ASSY HH	\$	392.00 L 2,149.85
PC	FRONT RADIATOR FAN MOTOR	\$	526.84
PC	FRONT RADIATOR FAN MOTOR COWLING	\$	498.80
PC	FRONT RADIATOR FAN BLADE	\$	244.50 x
PC	FRONT RADIATOR SPARE TANK	\$	298.00
PC	FRONT WIPER WASHER TANK	\$	178.10
PC	FRONT A/C CONDENSOR ASSY	\$	1,986.70
PC	FRONT A/C HIGH PRESSURE HOSE	\$	398.40
PC	FRONT A/C LOW PRESSURE HOSE	\$	681.20
PC	FRONT A/C DISCHARGE HOSE	\$	894.54

2PCS	FRONT A/C CONDENSOR SIDE COWLING LH / RH @ \$254.10 EACH	\$	508.20
1PC	FRONT SUPPORT PANEL (4)	\$	1,782.50
1PC	FRONT BRACE PANEL	\$	149.80
1PC	FRONT REINFORCEMENT BAR UPPER	\$	984.52
1PC	FRONT REINFORCEMENT BAR LOWER	S	699.81
1PC	FRONT REINFORCEMENT BAR BRACKET (TOP)	\$	1,094.50
1PC	FRONT RADAR ASSY	\$	3,895.15
1PC	FRONT RADAR BRACKET Hat	\$	984.05
1PC	FRONT WIPER GARNISH	\$	693.00

7,941.30

PARTS SUM: \$ 42,024.20 PARTS LESS 25%: \$ 10,506.05 PARTS TOTAL: \$ 31,518.15

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY FRONT NO. PLATE & GARNISH HM	\$	100.00 🔸
*	TO SUPPLY FRONT GRILLE CLIPS LLC	\$	50.00 15 -
*	TO SUPPLY LOWER GRILLE CLIPS HA	\$	50.00 ×
*	TO SUPPLY RADIATOR COOLANT HH	S	200.00 🗡
*	TO SUPPLY FRONT BUMPER CLIPS HA	S	50.00 🗶
*	TO SUPPLY FRONT BUMPER FOG LAMP GARNISH CLIPS HA	\$	50.00 ⊀
*	TO SUPPLY FRONT BUMPER LOWER GRILLE CLIPS	\$	50.00 🗶
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILIAT REPAIRS	E \$	300.00 H4
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & P.	ANELS \$	2,000.00 500 -
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$	2,000.00 400 -
*	TO TUFF COAT DAMAGED AREAS	\$	300.00 201-
*	TO RNR INTER-COOLER TO FACILITATE REPAIRS	\$	200.00-88 -
*	TO RNR FRONT RADIATOR ASSY & REFILL COOLANT TO FACIL	ITATE \$	200.00 ⊣⊣
	REPAIRS 103	J. W. 6	
*	TO RNR FRONT A/C CONDENSOR & REFILL A/C GAS TO FACILIT REPAIRS	ATL \$	200.00 ны
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$	200.00 30/
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ALL MEMORIES TO FACTORY DEFAULT SETTINGS	S. RESET \$	300.00 HH

LABOUR & S/N TOTAL: <u>\$ 6,250.00</u>

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 37,768.15

05 07 222 e 0930m

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: