

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Adeline Chng Pei Wen

Date: 27 Jul 2022

Preliminary Advice

Insured	: GBC111Z		
Vehicle No			
TP Vehicle No	: SHB8075B	Accident Date	: 02/07/2022
Make	: KIA OPTIMA	Assignment Date	: 04/07/2022
Date of Inspection	: 05/07/2022	Est. Duration of Repair	: 3
Inspection At	: PREMIER AUTOMOTIVE SERVICES PTE LTD (HQ) 23 CHANGI SOUTH AVE 2, #01-02 SINGAPORE 486443		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,784.90
Revised Amount	:S\$	1,277.50
Check Items (Estimated)	:S\$	94,40
Total	:S\$	1,371.90

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$

Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.