



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22006387/Ucy3e2	
			Date: 26/07/2022	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	YP 1648U	Veh. Inspected	SMS 9044K
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2202310/RUC	Excess (\$)	0.00
	Assign From	HENRY IRENE JAMES	Assign Date	05/07/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	mitsubishi attrage (A)	c.c	1193
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	MMBSTA13AKH004953	Colour	GREY
	Odometer	75615 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	185/55 R15	KUMHO	6 mm
	L/H Front Tyre	185/55 R15	KUMHO	6 mm
	R/H Rear Tyre	185/55 R15	KUMHO	6 mm
	L/H Rear Tyre	185/55 R15	KUMHO	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	04/07/2022	Inspection Date	05/07/2022
	Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	