



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22006394/Evy3e2	
			Date: 26/09/2022	
			Code: FCI2	
<b>1. Policy Particulars :- OWN DAMAGE</b>				
	<b>Insured Veh.</b>		<b>Veh. Inspected</b>	SLS 1640D
	<b>Policy No.</b>	D-21098055MVPC	<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	D22002032MVPC	<b>Excess (\$)</b>	500.00
	<b>Assign From</b>	AINI BINTE	<b>Assign Date</b>	05/07/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	AUDI A3	<b>c.c</b>	999
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2017
	<b>Chassis No.</b>	WAUZZZ8V1J1006593	<b>Colour</b>	RED
	<b>Odometer</b>	54718 KM	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
	<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	205/55 R18	GOODYEAR	5 mm
	<b>L/H Front Tyre</b>	205/55 R18	GOODYEAR	5 mm
	<b>R/H Rear Tyre</b>	205/55 R18	GOODYEAR	5 mm
	<b>L/H Rear Tyre</b>	205/55 R18	GOODYEAR	5 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	03/07/2022	<b>Inspection Date</b>	06/07/2022
	<b>Survey held at</b>	24 Benoi Sector. S629857		
	<b>Repairer</b>	PREMIUM AUTOMOBILES PTE LTD		
<b>5a. Remarks</b>				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE MARKET VALUE IS S\$78,000.00(EST. AVERAGE) C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>6 Working Days</b>	